

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-02849
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	B-2956
7. Lease Name or Unit Agreement Name	EAST VACUUM GB/SA UNIT TRACT 2175
8. Well No.	002
9. Pool name or Wildcat	VACUUM GB/SA

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	
2. Name of Operator Phillips Petroleum Company	
3. Address of Operator 4001 Penbrook Street, Odessa, TX 79762	
4. Well Location Unit Letter <u>M</u> : <u>660</u> Feet From The <u>SOUTH</u> Line and <u>660</u> Feet From The <u>WEST</u> Line Section <u>21</u> Township <u>17S</u> Range <u>35E</u> NMPM <u>LEA</u> County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3974' GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: CLEANED OUT AND ACIDIZED ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

7/26/94 MIRU. COOH W/RODS AND PUMP, NU BOP, COOH W/TBG.
7/27/94 TRIPPING IN WITH CASING SCRAPER TO 4250'. TRIPPING SAND PUMP. TAG @4627', CATCH SAMPLE OF IRON SULFIDE. TRIP IN W/PKR SET 4224'.
7/28-7/29/94 SWAB.
8/01/94 GIH W/DRILL COLLARS AND TBG. CLEAN OUT FROM 4627' TO 4637'. CIRC. CLEAN.
8/02/94 COOH CHANGE BIT SUB. GIH CLEAN OUT FILL TO 4650'. CIRC. CLEAN.
8/03/94 GIH W/PKR AND TBG. SET PKR @ 4200'. SWAB.
8/04/94 ACIDIZED WITH 2000 GALS 15% NEFE HCL ACID.
8/05/94 CHANGE OUT WELLHEAD. COOH W/TBG. LD PKR. GIH W/PROD TBG AND TAC. ND BOP. FLANGE UP WELLHEAD.
8/08/94 PU GIH W/PUMP AND RODS. RDMO DDU.
8/24/94 PUMP 24 HR TEST 18 BOPD 94 BWPD 1 MCF.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE [Signature] TITLE SUPERVISOR, REG. AFFAIRS DATE 11/02/94
TYPE OR PRINT NAME L. M. SANDERS TELEPHONE NO. 915/368-1488

(This space for State Use)

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY: