

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.
30-025-02851

Indicate Type of Lease
STATE ☒ FEE ☐

6. State Oil & Gas Lease No.
B-1040

7. Lease Name or Unit Agreement Name
**EAST VACUUM GB/SA UNIT
TRACT 2207**

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL ☒ GAS WELL ☐ OTHER

2. Name of Operator
Phillips Petroleum Company

8. Well No.
005

3. Address of Operator
4001 Penbrook Street, Odessa, TX 79762

9. Pool name or Wildcat
VACUUM GB/SA

4. Well Location
Unit Letter **L** : **1980** Feet From The **SOUTH** Line and **660** Feet From The **WEST** Line
Section **22** Township **17 S** Range **35 E** NMPM **LEA** County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
3942.7' GL

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. MIRU DDU. NU BOP. (CIBP STUCK AT 1400' WHILE GIH). KNOCK CIBP TO 4230'.
2. COOH. SET A 6-5/8" (24#) CIBP AT 4200'.
3. SPOT PLUG NO. 1 (25 SX CMT) 4200'-4140'. COVERS THE GB/SA.
4. PERFORATE 6-5/8" CSG AT 3000'. SQZ UNDER PKR W/PLUG NO. 2 (60 SX CMT) 3000'-2900'. COVERS THE YATES.
5. PERFORATE 6-5/8" CSG AT 1775'. SQZ UNDER PKR W/PLUG NO. 3 (60 SX CMT) 1775'-1675'. COVERS THE 9-5/8" SHOE AND SALT TOP.
6. PERFORATE 6-5/8" CSG AT 400'. PUMP PLUG NO. 4 (140 SX CMT) DOWN CSG, THRU PERFS AT 400' AND BACK TO SURFACE ON ANNULUS, LEAVING THE CSG FULL.
7. CUT OFF CSG 3' BELOW GROUND LEVEL. INSTALL MONUMENT MARKER. PERFORM RECLAMATION WORK.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE *M. Sanders* TITLE SUPERVISOR, REG. AFFAIRS DATE 3/31/95

TYPE OR PRINT NAME M. SANDERS TELEPHONE NO. 915/368-1488

(This space for State Use)

ORIGINAL SIGNED BY
GARY WINK
FIELD REP. II

APPROVED BY _____ TITLE _____ DATE APR 04 1995

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

10 1945

RECEIVED
OFFICE

10 1945

2045

10 1945