

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. B-2531
7. Unit Agreement Name
8. Farm or Lease Name Southern Pet. State
9. Well No. 1
10. Field and Pool, or Wildcat Vacuum (G-SA)
12. County Lea

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>
2. Name of Operator Penrose Production Company
3. Address of Operator Box 988, Eunice, New Mexico 88231
4. Location of Well UNIT LETTER M 330 FEET FROM THE South LINE AND 660 FEET FROM THE West LINE, SECTION 24 TOWNSHIP 17 S RANGE 37 E NMPM.
15. Elevation (Show whether DF, RT, GR, etc.)

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> OTHER <input type="checkbox"/>	REMEDIAL WORK <input checked="" type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> CASING TEST AND CEMENT JOB <input type="checkbox"/> OTHER <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/> PLUG AND ABANDONMENT <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

7-28-69 Pulled rods & tubing

7-29-69 Run wash pipe & cleaned out to 4576'

7-30-69 Frac well through 3½" tubing with 30000 gal. water and 25000 lb. sand.
Max. pressure 3700, min 3300. 24 bbls. @ min. ISDP 2200#, 15 min. 1850 #.

7-31-69 Run tubing & rods. Put well to pumping.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u><i>L. E. Crowell</i></u>	TITLE <u>Office Manager</u>	DATE <u>8-6-69</u>
SUPERVISOR DISTRICT 1		
APPROVED BY <u><i>[Signature]</i></u>	TITLE _____	DATE _____
CONDITIONS OF APPROVAL, IF ANY:		