

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. B-1839	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>		7. Unit Agreement Name
2. Name of Operator Chevron Oil Company		8. Farm or Lease Name State 5-27
3. Address of Operator P. O. Box 1660 Midland, Texas 79701		9. Well No. 3
4. Location of Well UNIT LETTER L 1930' FEET FROM THE North LINE AND 660' FEET FROM THE West LINE, SECTION 27 TOWNSHIP 17-S RANGE 35-E NMPM.		10. Field and Pool, or Wildcat Vacuum (Grbg.-SA)
15. Elevation (Show whether DF, RT, GR, etc.) 3943' DF		12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Move in and rig up pulling unit. Clean out to approximately 4620'. Run packer on 3 1/2" tubing and fracture treat with total of 36,000 gallons gelled salt water and 51,000 lbs. of sand in 3 stages. Pull tubing and packer and clean out. Run tubing and rods and place on production

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>J. E. Pullig</u>	TITLE <u>Sr. Drilling Supervisor</u>	DATE <u>December 10, 1971</u>
APPROVED BY <u>[Signature]</u>	TITLE <u>SPECIAL AGENT IN CHARGE</u>	DATE <u>DEC 13 1971</u>
CONDITIONS OF APPROVAL, IF ANY:		

RECEIVED

DEC 13 1971

OIL CONSERVATION COMM.
HOODS, N. M.