

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs NM 88241-1980

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

2040 Pacheco St.
Santa Fe, NM 87505

WELL API NO.	30-025-02910
5. Indicate Type of Lease	STATE ☒ FEE ☐
6. State Oil & Gas Lease No.	A-1320
7. Lease Name or Unit Agreement Name	EAST VACUUM GB/SA UNIT TRACT #2801
8. Well No.	009
9. Pool name or Wildcat	VACUUM GRAYBURG/SAN ANDRES

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER	
2. Name of Operator Phillips Petroleum Company	
3. Address of Operator 4001 Penbrook Street Odessa, TX 79762	
4. Well Location Unit Letter <u>N</u> : <u>660</u> Feet From The <u>SOUTH</u> Line and <u>1992</u> Feet From The <u>WEST</u> Line Section <u>28</u> Township <u>17S</u> Range <u>35E</u> NMPM LEA County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	3945' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐		CASING TEST AND CEMENT JOB ☐	
OTHER: ☐		OTHER: <u>CLEAN OUT T/4660', ACIDIZE & RET T/PROD</u> ☒	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

05/26/98 DWN DUE T/PARTED POL ROD, RODS & PMP PULLED, NU BOP & PAN, COOH W/TBG, TAG FILL @ 4615', REC SAMPLE CALCIUM CARBONATE SCALE, GIH W/KS TBG, WK CHGD F/RTP T/WKOVER.
05/27/98 COOH W/KS, PU GIH W/4-3/4" BIT, 6 3-1/2" DCS & TBG, TAG FILL @ 4596', PMP T/BRK CIRC, PMP 650 BBL COULDN'T GET CIRC, MIRU ADDITIONAL PMP, BRK CIRC, CO FILL F/4596-4665', CIRC CLEAN, PULL UP INTO CSG.
05/28/98 COOH W/BIT, CHG BIT SUB T/JET WASH SUB, GIH W/JET WASH SUB, JET WASH OPEN HOLE F/ 4125-4665', CIRC CLN, COOH, LD COLLARS & BIT, MIRU TBG TSTRS, PU PKR, TST IN HOLE W/TBG, SET PKR @ 4060'.
05/29/98 LD & TST BKSIDE T/1000# F/30 MIN OK, MIRU HES, PMP 3000 GAL 15% FERCK ACID, 2500# ROCK SALT & 2500# 100 MESH SALT IN 63 BBL GELLED BRINE & 36 BBL FW FLUSH: 1000 GALS
(CONTINUED ON BACK)

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

TITLE Senior Regulation Analyst

DATE

7-1-98

TYPE OR PRINT NAME

Larry M. Sanders

TELEPHONE NO. (915) 368-1488

(This space for State Use)

ORIGINAL SIGNED BY

APPROVED BY

TITLE

DATE

JUL 16 1998

CONDITIONS OF APPROVAL, IF ANY:

EVAC #2801-009

05/29/98 CONTINUED

ACID; 1000# RK & 1000# 100 MESH SALT IN 31 BBL BRINE; 1000 GAL ACID; 1500# RK & 1500# 100 MESH SALT IN 32 BBL BRINE; 1000 GALS ACID; 36 BBL FLUSH, ISIP 924# 5 MIN 410# 10 MIN 200# 15 MIN 80# AVG PRESS 880# MAX PRESS 1632# AVG RATE 5.5 BPM, RDMO HES, RU SWAB, OPEN UP W/TBG ON VAC & FL @ 300', REC 135 BBL WTR W/END FL @ 1700'.

06/01/98 OPEN UP W/25# ON TBG & FL @ 1300', RECOVER 88 BBL WTR W/END FL @ 1500', RD SWAB, MIRU PMP TRK, PMP SCALE SQZ: MIX & PMP 3 DRUMS TH-757 IN 60 BBL FW, FLUSH W/300 BBL FW, WO PRESS T/FALL OFF, COOH LD PKR, GIH W/PROD TBG.

06/02/98 ND PAN & BOP, FLNG UP WH, HK WH UP T/FLOWLINE, GIH W/PMP & RODS, SPACE OUT, HANG ON, LD & TST, RDMO DDU, START PMPG, PMP 18 HRS, NO TST.

06/03/98 PMP 24 HRS, NOT TST.

06/04/98 PMP 24 HRS, NOT TST.

06/05/98 PMP 24 HRS, NOT TST.

06/06/98 PMP 24 HRS, NOT TST.

06/08/98 PMP 24 HRS, TST: 3.8 BOPD 458.1 BWPD 107.4 MCF 81.1% CO2

TEMP DROP F/REPORT

06/29/98 PU F/REPORT #8 DATED 6/08/98, PMP 24 HRS, TST: 9.6 BOPD 278.0 BWPD, 257.0 MCF.

06/30/98 PMP 24 HRS, TST: 9.6 BOPD 296.6 BWPD 257.7 MCF

07/01/98 PMP 24 HRS, TST 10.6 BOPD 298.3 BWPD 251.5 MCF

COMPLETE DROP F/REPORT

