

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-02914
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. A-1320
7. Lease Name or Unit Agreement Name East Vacuum Gb/SA Unit Tract 2801
8. Well No. 014
9. Pool name or Wildcat Vacuum GB/SA

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	
2. Name of Operator Phillips Petroleum Company	
3. Address of Operator 4001 Penbrook St., Odessa, TX 79762	
4. Well Location Unit Letter L : 660 Feet From The West Line and 1980 Feet From The South Line Section 28 Township 17S Range 35E NMPM Lea County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3952' GL, 3964' RKB	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. MIRU DDU. NU Class I BOP. Lay down rods, pump, tubing, and packer. Set a 5-1/2" CICR at 4050' w/2-3/8" workstring.
2. Squeeze under retainer with Plug No. 1 (125 sx cement) 4050'-4640'. Cap retainer with 10 sx cement. This will cover the San Andres and Grayburg. Circulate 5-1/2" casing with 9.5 ppg mud laden fluid.
3. Spot Plug No. 2 (25 sx cement) 2900'-3000'. This will cover the Yates.
4. Spot Plug No. 3 (25 sx cement) 1500'-1650'. This will cover the salt top and the 7-5/8" casing shoe.
5. Spot Plug No. 4 (30 sx cement) 3'-300'. This will cover the 10-3/4" casing shoe, fresh water, and surface plug.
6. Cut off casing 3' below ground level. Install monument marker. Perform reclamation work.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE L. M. Sanders TITLE Supv. Regulatory Affairs DATE 04-29-94  
TYPE OR PRINT NAME L. M. Sanders (915) TELEPHONE NO. 368-1488

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON  
DISTRICT I SUPERVISOR

APPROVED BY \_\_\_\_\_ DATE MAY 03 1994

CONDITIONS OF APPROVAL, IF ANY:

THE COMMISSION MUST BE NOTIFIED 24  
HOURS PRIOR TO THE BEGINNING OF  
PLUGGING OPERATIONS FOR THE WELL  
TO BE APPROVED.

RECEIVED

MAY 02 1994

JOHN HUBBS  
OFFICE