

**DISTRICT I**  
P.O. Box 1980, Hobbs, NM 88240  
**DISTRICT II**  
P.O. Box Drawer DD, Artesia, NM 88210  
**DISTRICT III**  
1000 Rio Brazos Rd., Aztec, NM 87410

**OIL CONSERVATION DIVISION**  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

<b>SUNDRY NOTICES AND REPORTS ON WELL</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30 025 02939
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
2. Name of Operator TEXACO EXPLORATION & PRODUCTION INC.		6. State Oil / Gas Lease B-2423
3. Address of Operator P.O. BOX 730, HOBBS, NM 88240		7. Lease Name or Unit Agreement Name CENTRAL VACUUM UNIT
4. Well Location Unit Letter <u>A</u> : <u>330</u> Feet From The <u>NORTH</u> Line and <u>990</u> Feet From The <u>EAST</u> Line Section <u>30</u> Township <u>17S</u> Range <u>35E</u> NMPM <u>LEA</u> COUNTY		8. Well No. 1
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3981' GL		9. Pool Name or Wildcat VACUUM GRAYBURG SAN ANDRES

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPERATIONS <input type="checkbox"/>
OTHER: <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: CASING INTEGRITY TEST FOR TA STATUS <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1/5/94 - 1/6/94

1. NOTIFIED NMOCD. TOH W/ PRODUCTION EQUIPMENT.
2. SET CIBP @ 4295' & CAPPED W/ 35' CMT, PBTD @ 4260'.
3. CIRCD HOLE W/ INHIBITED FLUID & TSTD AS PER NMOCD GUIDELINES TO 500# FOR 30 MIN, HELD OK.
4. TOH W/ TBG. REQUEST TEMPORARILY ABANDON WELL STATUS THROUGH 1/1/99.

(ORIGINAL CHART ATTACHED, COPY OF CHART ON BACK)

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Monte C. Duncan TITLE Engr Asst DATE 1/19/94  
 TYPE OR PRINT NAME Monte C. Duncan Telephone No. 397-0418

(This space for State Use)

**ORIGINAL SIGNED BY JERRY SEXTON**

APPROVED BY DISTRICT I SUPERVISOR

CONDITIONS OF APPROVAL, IF ANY:

**This Approval of Temporary  
Abandonment Expires 1-1-99**

DATE JAN 24 1994

DeSoto/Nichols 12-93 ver 1.0

SAD

PRINTED IN U.S.A. 67

