NEW I GICO OIL CONSERVATION COMM ION

Santa Fe, New Mexico

MISCELLANEOUS NOTICES

Submit this notice in triplicate to the Oil Commission or its proper agent before the work specified is to begin. A copy will be returned to the sender on which will be given the approval, with any modifications considered advisable, or the rejection by the Commissioner or agent, of the plan submitted. The plan as approved should be followed, and work should not begin until approval is obtained. See additional instructions in the Rules and Regulations of the Commission.

Indicate nature of notice by checking below:

| NOTICE OF INTENTION TO TEST SHUT-OFF | CASING | NOTICE OF INTENTION TO SHOOT CHEMICALLY TREAT WELL | OR |
|---|---------------------------|---|------------------|
| NOTICE OF INTENTION TO CHAN | | NOTICE OF INTENTION TO PULL OTHERWISE ALTER CASING | OR |
| NOTICE OF INTENTION TO REPA | IR WELL | | |
| NOTICE OF INTENTION TO DEEP | EN WELL | NOTICE OF INTENTION TO PLUG | WELL |
| | Hobbs, New Me | xico, February 4, 1939 | |
| | | Place | Date |
| OIL CONSERVATION COMMISSIO Santa Fe, New Mexico. | N, | | 7 |
| Gentlemen: | | Treat A | |
| | | described below at the | |
| The Ohio Oil Company | State Sta | plin Well No. 2 | in NE 1841 |
| Company or Operator | Lease . R. 35 E | , N. M. P. M., | heid. |
| ♥ | County. | A1. A2. A . A/A | Terus |
| | | ROPOSED PLAN OF WORK | |
| | | ES AND REGULATIONS OF THE COMM | ISSION |
| Plan to run 4100' of 7" 0 | asing and come | nt with 700 sacks Oil Well Ces | ent. |
| | | | |
| | | Ø _N | |
| | | | _ |
| | | 11 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 | 1000 |
| | | | . ***//) |
| | | MOBSOTT | |
| | | | SUJ |
| | | **C | E |
| FEB 6 - 1939 | | | |
| Approved | | The Ohio Oil Company | |
| except as follows: | | By Company or Operator | Dish |
| | | | |
| | | Position Supt Send communications regard | ling well to |
| OIL CONSERVATION CO | MM4ssion, | Name The Ohio Oil Company | |
| By Y O yarlerock | rki . | - Address Hobbe, New Mexic | |
| Title OIL & GAS III. Prode | | - | |
| Title OIL & GAS IIII. Record | }f t | - | |

1.7

A supplied to the supplied of the supp

An east

in distribution of the second

na santa di Carante de Carante de

 $\mathbb{E}[\widehat{\mathcal{M}}(x,\underline{\Sigma}(x))] = \frac{1}{2} (1 + \epsilon x^2 + \epsilon x^$