

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

6a. Indicate Type of Lease
State ☒ Fee ☐
5. State Oil & Gas Lease No.
B-1501

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PROPOSAL" (Form C-101) FOR SUCH PROPOSALS.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	7. Unit Agreement Name Central Vacuum Unit
2. Name of Operator TEXACO Inc.	8. Form or Lease Name Central Vacuum Unit
3. Address of Operator P. O. Box 728, Hobbs, New Mexico 88240	9. Well No. 18
4. Location of Well UNIT LETTER J 1980 FEET FROM THE East LINE AND 1980 FEET FROM THE South LINE, SECTION 30 TOWNSHIP 17-S RANGE 3-E N.M.P.M.	10. Field and Pool, or Wellcut Vacuum Grayburg San Andres
11. Elevation (Show whether DF, RT, GR, etc.) 3982.5 (GR)	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPER. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☒ Deepen in same Zone & treat	CASING TEST AND CEMENT JOBS ☐	OTHER ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Rig up. Pull rods & pump. Install BOP. Pull tubing.
2. Deepen from 4667' to 4702' (35')
3. Log well.
4. Set pkr. @ approx. 3600'. Acidize w/6000 gal. 20% NE-FE Hcl Acid in 4-stages using 100# Benzoic Acid Flakes & 200# rock salt between stages.
5. Install production equipment. Test & place on production.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Jerry Sexton TITLE Asst. Dist. Supt. DATE 5-14-80
APPROVED BY Dick L. Supt. TITLE _____ DATE MAY 15 1980

CONDITIONS OF APPROVAL, IF ANY: