

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-02946
5. Indicate Type of Lease	STATE ☒ FEE ☐
6. State Oil / Gas Lease No.	857943
7. Lease Name or Unit Agreement Name	CENTRAL VACUUM UNIT
8. Well No.	20
9. Pool Name or Wildcat	VACUUM GRAYBURG SAN ANDRES
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	

SUNDY NOTICES AND REPORTS ON WELL
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. Name of Operator
TEXACO EXPLORATION & PRODUCTION INC.

3. Address of Operator
205 E. Bender, HOBBS, NM 88240

4. Well Location
Unit Letter L : 980 Feet From The SOUTH Line and 621 Feet From The WEST Line
Section 30 Township 17S Range 35E NMPM LEA COUNTY

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒ ALTERING CASING ☐
COMMENCE DRILLING OPERATION ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

3-23-98: MIRU. UNLOAD, RACK TALLY WS. NUBOP. TIH W/BENT JOINT, & WS TO 1643'.
3-24-98: TIH TO 2508'. ATT TO WRK INTO PARTED CSG. TIH W/IB TO 2508'. TIH W/BENT JOINT, & WS TO 2508'. WRK INTO PARTAED CSG. TIH TO 2854'.
3-25-98: TAG @ 4710'. DIG OUT WH. BREAK OUT WH.
3-26-98: TIH & LAND TBG. BACK OFF TBG @ 103'. TIH & SET RBP @ 24'. NDBOP & WH. RAN CSG SPEAR, SPEAR CSG & WRK CSG FREE. ND CSG HEAD. TAKE OFF & CHECK THREADS. NUWH. SET BOP.
3-27-98: ND CSG HEAD & CHANGE OUT. NUBOP ON 7 5/8" CSG. FSH RBP @ 24' OUT OF 5 1/2" CSG. CIRC CSG ANNULUS. WRK 5 1/2" CSG. WRK FREE 20'.
3-31-98: LOAD OLD CSG & CLN LOC. UNLOAD, RACK, TALLY 5 1/2" CSG.
4-01-98: RAN 5 1/2" CSG 2499.7'. RU REV EQPT & WSH OUT FOR SCREW IN. SCREW INTO 5 1/2" CSG @ 2499'. LAND 5 1/2" CSG. SET SLIPS & PACK OFF. ND BOP. NU 5 1/2" BOP.
4-02-98: TIH W/2 7/8" TBG TO 104'. SCREW INTO 2 7/8" TBG. WRK STUCK TBG FREE. PULL BTM OF TBG TO 3450'.
4-03-98: TIH W/BIT & CSG SCRAPER & WS TO 2500-2503'. RUN BIT TO 4066'. TIH W/RBP ON WS. RBP @ 4031'.
4-04-98: TIH W/PKR ON WS. PSA 3937'. TEST RBP @ 4031' TO 500#-OK. RAISE PKR TO 2401'. TEST 2401-4031' TO 300#-OK.
4-06-98: RAN ULTRA SONIC IMAGE LOG FR 4019-2400'.
4-07-98: HLE @ 2511'. CMT BOND UP @ 2560'. TIH W/RETR TOOL ON 2 7/8" TBG & REL RBP @ 4031'. PULL UP & SET @ 2401'. CIRC HLE W/FW. NDBOP. INSTL TBG HEAD. NUBOP. TIH W/RETR TOOL ON TBG. REL RBP @ 2401'.
4-08-98: TIH W/BIT & BAILER. TAG BRIDGE @ 4670'. TIH W/PKR & SET @ 4001'.
4-09-98: ACIDIZE 4083-4710' W/10,000 GAL 15% NEFE & 3500# RK SLT. SWAB & RECVD 20 BBLS LOAD.
4-10-98: FL @ 1200'. END FL @ 2000'.
4-13-98: RD SWAB. REL PKR.
4-14-98: TIH W/MA, PERF SUB, TBG. MA @ 4685'. SN @ 4651'. TAC @ 4013'. NDBOP. NUWH.
4-15-98: RAN GAS ANCHOR, PMP, SNKR BARS & RODS. RD 4-16-98. WELL ON TEST.
4-24-98: ON 24 HR OPT. PUMPED 17 BO, 206 BW, & 5 MCF. FINAL REPORT

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J. Denise Leake TITLE Engineering Assistant

DATE 4/24/98

TYPE OR PRINT NAME J. Denise Leake

Telephone No. 397-0405

(This space for State Use)

ORIGINAL SIGNED BY CHUCK WILLIAMS

APPROVED BY DATE TITLE

CONDITIONS OF APPROVAL, IF ANY:

DATE