

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
B-1722	

<p>SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)</p>		
<p>1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/></p>		<p>7. Unit Agreement Name Central Vacuum Unit</p>
<p>2. Name of Operator TEXACO Inc.</p>		<p>8. Farm or Lease Name Central Vacuum Unit</p>
<p>3. Address of Operator P. O. Box 728, Hobbs, New Mexico 88240</p>		<p>9. Well No. 20</p>
<p>4. Location of well UNIT LETTER <u>L</u> <u>1980</u> FEET FROM THE <u>South</u> LINE AND <u>621</u> FEET FROM THE <u>West</u> LINE, SECTION <u>30</u> TOWNSHIP <u>17-S</u> RANGE <u>35-E</u> NMPM.</p>		<p>10. Field and Position of Wellcat Vacuum Grayburg San Andres</p>
<p>15. Elevation (Show whether DF, RT, GR, etc.) 4001' (DF)</p>		<p>12. County Lea</p>

<p>16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data</p>			
NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <u>Deepen in San Andres</u> <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. RIG UP. PULL RODS AND PUMP. INSTALL BOP. PULL TUBING.
2. DEEPEN TO 4710'. LOG WELL.
3. SET PACKER @ 3650'. ACIDIZE W/8200 GALS 15% NEFE HCL ACID AND 1 DRUM SCALE INHIBITOR IN 4-EQUAL STAGES USING 400# MOTH BALLS AND 400# ROCK SALT BETWEEN STAGES. FLUSH.
4. INSTALL PRODUCTION EQUIPMENT. TEST AND RETURN TO PRODUCTION.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Jerry Sexton TITLE Asst Dist Mgr DATE 11-15-83
ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR
APPROVED BY _____ TITLE _____ DATE NOV 18 1983
CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

NOV 17 1983

C.C.D.
HOBBS OFFICE