

DUPLICATE

NEW MEXICO OIL CONSERVATION COMMISSION  
Santa Fe, New Mexico

RECEIVED  
OCT 16 1940  
RECEIVED

MISCELLANEOUS REPORTS ON WELL

Submit this report in triplicate to the Oil Conservation Commission or its proper agent within ten days after the work specified is completed. It should be signed and sworn to before a notary public for reports on beginning drilling operations, results of shooting well, results of test of casing shut-offs, result of plugging of well, and other important operations, even though the work was witnessed by an agent of the commission. Reports on minor operations need not be signed and sworn to before a notary public. See additional instructions in the Rules and Regulations of the Commission.

HOBBS OFFICE

Indicate nature of report by checking below:

REPORT ON BEGINNING DRILLING OPERATIONS		REPORT ON REPAIRING WELL	
REPORT ON RESULT OF SHOOTING OR CHEMICAL TREATMENT OF WELL		REPORT ON PULLING OR OTHERWISE ALTERING CASING	
REPORT ON RESULT OF TEST OF CASING SHUT-OFF		REPORT ON DEEPENING WELL	
REPORT ON RESULT OF PLUGGING OF WELL		Installation of flow packer	x

Dallas, Texas

10-11-40

OIL CONSERVATION COMMISSION,  
Santa Fe, New Mexico.

Place

Date

Gentlemen:

Following is a report on the work done and the results obtained under the heading noted above at the

Westmount Oil Company State "B" Well No. 2 in the  
COMPANY OR OPERATOR LEASE  
NW NE NW of Sec. 30 T. 17S R. 35E N. M. P. M.,  
Vacuum Field, Lea County

The dates of this work were as follows: August 14-15, 1940

Notice of intention to do the work ~~was~~ (was not) submitted on Form C-102 on \_\_\_\_\_ 19\_\_\_\_  
and approval of the proposed plan ~~was~~ (was not) obtained. (Cross out incorrect words)

DETAILED ACCOUNT OF WORK DONE AND RESULTS OBTAINED

Prior to installation of flow packer, well died for lack of sufficient gas to maintain column of fluid in tubing. Tubing was pulled and 5 1/2" American Flow Packer, 477'6" from bottom of tubing. Total tubing and packer rerun - 467'6". Total tubing above packer - 4194'6". Total tubing below packer - 477'6". Length of packer - 4'8". Packer set in casing 27' off bottom. Bottom of casing - 4221'6". On test after packer set, well flowed 151 bbls of oil in 16 hours. Gas/oil ratio test has not been taken since installation of flow packer.

OIL CONSERVATION COMMISSION  
RECEIVED  
OCT 14 1940  
RECEIVED

Witnessed by H. B. Jewell  
Name

M. J. Delaney Co.  
Company

Title

Subscribed and sworn to before me this 11th

day of October, 19 40  
Virginia Horton  
Notary Public

I hereby swear or affirm that the information given above is true and correct.

Name John M. Turner  
Position Prod Asst

Representing Westmount Oil Company  
Company or Operator

My Commission expires 6-1-41

Address Dallas, Texas

Remarks:

Roy Garbrough  
Name  
OIL & GAS INSPECTOR  
Title

The first part of the document discusses the importance of maintaining accurate records of all transactions. It emphasizes that proper record-keeping is essential for the integrity of the financial system and for the ability to detect and prevent fraud. The document also notes that records should be kept for a sufficient period of time to allow for a thorough review if necessary.

In addition, the document outlines the responsibilities of those who are responsible for maintaining these records. It states that they must ensure that all transactions are recorded accurately and in a timely manner. It also mentions that they should be able to provide a clear and concise explanation of the records when requested. The document further notes that any discrepancies or irregularities should be reported immediately to the appropriate authorities.

The second part of the document discusses the importance of maintaining accurate records of all transactions. It emphasizes that proper record-keeping is essential for the integrity of the financial system and for the ability to detect and prevent fraud. The document also notes that records should be kept for a sufficient period of time to allow for a thorough review if necessary.

In addition, the document outlines the responsibilities of those who are responsible for maintaining these records. It states that they must ensure that all transactions are recorded accurately and in a timely manner. It also mentions that they should be able to provide a clear and concise explanation of the records when requested. The document further notes that any discrepancies or irregularities should be reported immediately to the appropriate authorities.

The document concludes by reiterating the importance of maintaining accurate records and the responsibilities of those who are responsible for this task. It states that proper record-keeping is a fundamental part of any financial system and that it is essential for the system to function properly and to be able to detect and prevent fraud.