

OIL CONSERVATION DIVISION

P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
B-387	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT..." (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator	Central Vacuum Unit
3. Address of Operator	8. Farm or Lease Name
P.O. Box 728, Hobbs, New Mexico 88240	Central Vacuum Unit
4. Location of Well	9. Well No.
UNIT LETTER K, 1980 FEET FROM THE South LINE AND 1980 FEET FROM	75
THE West LINE, SECTION 31 TOWNSHIP 17-S RANGE 35-E NMPM.	10. Field and Pool, or Wildcat
	Vacuum Grayburg
	San Andres
15. Elevation (Show whether DF, RT, GR, etc.)	12. County
3990' (GR)	Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Rig up, pull rods and pump, install BOP, pull tubing.
2. Clean out to 4660, drilled plug 4660 - 4700 PBTD.
3. Acidize OH 4098 - 4708 w/10,000 gals. 20% NEFE Acid in 5-equal stages using 750# Benzoil Acid flakes.
4. Ran tubing, pump & rods.
5. Test & return to production.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Jerry Sexton TITLE Assistant District Mgr. DATE 4-22-82

ORIGINAL SIGNATURE

APPROVED BY JERRY SEXTON TITLE DATE APR 26 1982

CONDITIONS OF APPROVAL 1 SUPP.

RECORDED

APR 23 1962

O.C.D.
HOBBS OFFICE