NEW METICO OIL CONSERVATION COMMISCON

Santa Fe, New Mexico

MISCELLANEOUS NOTICES

Submit this notice in triplicate to the Oil Conservation Commission or its proper agent before the work specified is to begin. A copy will be returned to the sender on which will be given the approval, with any modifications considered advisable, or the rejection by the Commission or its agent, of the plan submitted. The plan as approved should be followed, and work should not begin until approval is obtained. See additional instructions in the Rules and Regulations of the Commission.

NOTICE OF INTENTION TO TEST C	CASING	NOT	ICE OF INT	ENTION TO	SHOO'	T OR	T
SHOT-OFF		X (CHEMICALL	Y TREAT W	VELL		
NOTICE OF INTENTION TO CHANG	GE PLANS	NOT	ICE OF INTE	ENTION TO ALTER CA	PULL C	O'R	
NOTICE OF INTENTION TO REPA	IR WELL	NOT	ICE OF INTE	ENTION TO	PLUG V	WELL	
NOTICE OF INTENTION TO DEEPE	N WELL						-
	Hobbs,	New Mexico	Place	Арт	-il 13	, 1938 Date	L
OIL CONSERVATION COMMISSION	٦,						
Santa Fe, New Mexico.							
Gentlemen:							
Following is a notice of intention to do	certain work as	described belo	w at the				
The Ohio Oil Gompany Company or Operator	Lease	e varn		Well No		in K	4
of Sec. 31, T. 17, 8, F	R. 35 E , N	. M. P. M.,		Vaqu			
Loa							
	-						
FULL I	DETAILS OF F	PROPOSED I	PLAN OF V	WORK			
				·	OBERE	107017	
FULL I FOLLOW INSTRUCTION to run 500 feet of 9 5/8"	NS IN THE RUI	LES AND REC	GULATIONS	OF THE C			nt
FOLLOW INSTRUCTION	NS IN THE RUI	LES AND REC	GULATIONS	OF THE C			nt
FOLLOW INSTRUCTION	NS IN THE RUI	LES AND REC	GULATIONS	OF THE C	1 We1		nt
FOLLOW INSTRUCTION	NS IN THE RUI	LES AND REC	GULATIONS	OF THE C	1 We1		nt
FOLLOW INSTRUCTION	NS IN THE RUI	LES AND REC	GULATIONS	OF THE C	1 We1		nt
FOLLOW INSTRUCTION	NS IN THE RUI	LES AND REC	GULATIONS	OF THE C	1 We1		nt
FOLLOW INSTRUCTION	NS IN THE RUI	LES AND REC	SULATIONS The 500 sac	OF THE C	1 We1	1 Come	nt
FOLLOW INSTRUCTION	NS IN THE RUI	LES AND REC	SULATIONS The 500 sac	OF THE C	1 Well 1938 1938	1 Come	nt
FOLLOW INSTRUCTION	NS IN THE RUI	LES AND REC	SULATIONS The 500 sac	OF THE C	1 Well 1938 1938	1 Come	nt
FOLLOW INSTRUCTION	NS IN THE RUI	LES AND REC	SULATIONS The 500 sac	OF THE C	1 Well 1938 1938	1 Come	nt
to run 500 feet of 9 5/8"	NS IN THE RUI	LES AND REC	SULATIONS The 500 sac	OF THE C	1 Well 1938 1938	1 Come	nt
to run 500 feet of 9 5/8"	NS IN THE RUI	LES AND REC	SULATIONS The Sol Back His	OF THE C	1938 1938	1 Come	nt
to run 500 feet of 9 5/8° APR 15 1938	NS IN THE RUI	LES AND REC	HI	OF THE C	1 Well 1938 17 G	1 Come	nt
to run 500 feet of 9 5/8° APR 1 5 1938	NS IN THE RUI	LES AND REC	HI	OF THE CORRESPONDENCE	1938 1938	1 Come	nt
to run 500 feet of 9 5/8"	NS IN THE RUI	By Position	HI Lewis	OF THE CONTROL OF THE	1 We 1: 1938 17 15 1938 17 15 15 15 15 15 15 15 15 15 15 15 15 15	1 Come	nt
to run 500 feet of 9 5/8° APR 1 5 1938	Casing and	By Position	Send commun	OF THE CONTROL OF THE	1938 J L Compared or L garding	Come	nt