د د د د هغاله د ادری _{ایر} د هوار س	Age for	-
RGY AND MINERALS DEPA	ARTMENT	
	OIL ONSERVATION DIVISION	
DISTRIBUTION	P. O. BOX 2088	Form C-103 · Revised 10-1-78
SANTA FE	SANTA FE, NEW MEXICO 87501	RETISED 10-1-70
PILE		Sa. Indicate Type of Lease
V.3.0.1.		State X Fee
LAND OFFICE		5. State Oll 6 Gas Lease No.
OPERATOR		
	API 30-025-02960	B-1527
	UNDRY NOTICES AND REPORTS ON WELLS	
		7. Unit Agreement Name
VELL X GAS WELL	0THCR-	East Vacuum Gb/SA Unit
me of Operator		8. Farm of Lease Hame
		East Vacuum Gb/SA Unit
	coleum Company	9. Well No. Tr. 3127
dress of Operator		001
Rm 401, 4001	Penbrook St., Odessa, Texas .79762	
cation of Well		10. Field and Pool, or Wildcai
J	. 1980 FEET FROM THE SOUTH LINE AND 1980 FEET FROM	Vacuum Gb/SA
WRIT LETTLA		
Fact	SECTION 31 TOWNSHIP 17-S RANGE 35-E HAPPA	$\Delta M M M M M M M M M M M M M M M M M M M$
THELASLLINE	, SECTION TOWNSHIP RANGE RANGE	`\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\
,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	15. Elevation (Show whether DF, RT, GR, etc.)	12. County
		Lea
	N/A	
C	heck Appropriate Box To Indicate Nature of Notice, Report or Ot	her Data
NOTICE	OF INTENTION TO: SUBSEQUEN	T REPORT OF:
•		
ORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING ·
	COMMENCE DRILLING OPHS.	PLUS AND ABANDONMENT
POBARILY ABANDON	CHANGE PLANS	
. DR ALTEN CASING		
	Acidize	
underream &	Aciaize	
	leted Operations (Clearly state all pertinent details, and give pertinent dates, including	estimated date of station any proposed
Describe Proposed or Comp.	ieted Operations (creatly state all pertinent actails, and give pertinent autes, including	*!! hobore

opril SEE RULE 1103.

lecommended procedure to underream open hole section from 4340' to TD (4667') and acidize: NU DDU and reverse unit. Install BOP. POOH with tubing and submersible pump. RIH with a 6-1/8" bit and nine 4-3/4" drill collars on a 2-7/8" workstring to \pm 4095'. Mud up with fresh water, Bentonite, and Drisco CMC as needed and establish circulation. (Estimated BHP = 1600 psi.) Clear but hole to \pm 4667'. RIH with 5-3/4" OD underreamer with piston stops set for reaming an 8-1/2" iole and nine 4-3/4" drill collars. Underream open hole from 4340' to ± 4667' (327'). RIH with 5-1/8" bit and clean out to TD. GIH with RTTS-type packer and 620' of tailpipe on a 2-7/8" vorkstring. While GIH test tubing to 5000 psi. With tail pipe just off bottom (keep pkr. inside sg.) spot 1000 gallons of 15% HCl, containing appropriate quantities of inhibitor, iron sequestering agent, and non-emulsifying agent, in the open hole interval. Pull up and set packer at 3710'. (End of tubing at 4330'.) Swab to clean up. Load annulus with 2% KCl water and test casing and packer to 500 psi. Hold this pressure on the annulus during the following acid treatment. Test all surface lines to 5500 psi prior to acid treatment. Acidize the open hole interval with 15,000 gallons 15% cross-linked HCl, containing appropriate quantities of breaker, inhibitor, iron sequestering agent, and non-emulsifying agent, and 3,000 gallons 15% HCl. Shut well in for 1 hour. Release packer and lower the tailpipe to 4610'. Spot 50 bbls. of crude oil in the open hole to aid dissolution of the BAF. POOH with tubing and leave well shut in overnight. RIH with submersible pumping unit and tubing. Set bottom of submersible motor at 4500'.

nareby certify that the information above is true and complete to the best of my knowledge and belief.

. Poph J. Roper for W. J. Mueller	TITLE DA1	June 14, 1985
ORIGINAL SIGNED BY JERRY SEXTON DISTRICT I SUPERVISOR	915/367-12	57 (MCLemore) 1985 -
DITIONS OF APPROVAL, IF ANYI		

RECEIVED

£

•

JUN 1 4 1985