

			•	_
	<i>LANE</i>	OUS NOTICE	ES	
Submit this notice in triplicate to the Oil Conservat begin. A copy will be returned to the sender on advisable, or the rejection by the Commission or ag and work should not begin until approval is obta the Commission.	TTPhiah III	III ha miyan tha ghnrau	vat with any modifications c	onsidered
	e of not	ice by checking below	:	
NOTICE OF INTENTION TO TEST CASING SHUT-OFF		CHEMICALLY	TION TO SHOOT OR TREAT WELL	x
NOTICE OF INTENTION TO CHANGE PLANS		NOTICE OF INTENTION TO PULL OR OTHERWISE ALTER CASING		
NOTICE OF INTENTION TO REPAIR WELL	X	NOTICE OF INTE	NTION TO PLUG WELL	
NOTICE OF INTENTION TO DEEPEN WELL				
	Nid	land, Texas	August 1, 1950	
		Place	Date	
Gentlemen: Following is a notice of intention to do certain we Humble Oil & Refining Company N	ork as de	scribed below at the_	2	NW/L of NE/
Humble Oil & Refining Company N	i. N. S	tate "K"	Well No. in	NW/4 of NE/
Company or Operator L	_ease			
of Sec. 32 , T. 17-8 , R. 35-E	, N	. M. P. M.,	racuus	Field.
County				
FULL DETAILS O		- -		
FOLLOW INSTRUCTIONS IN THE R	RULES A	ND REGULATIONS	OF THE COMMISSION	
	_		(2)	
Total depth of well 4675'.			allaws. (I) Isad ass	_
and tubing with oil, (2) pull 3/4" t	ubing,	(3) acidize wit	th 10,000 gallons ac	id,
(4) swab and test well and (5) run t	ubing, tubing	(3) acidize wit	th 10,000 gallons ac	id,
and tubing with oil, (2) pull 3/4" t (4) swab and test well and (5) run t pump.	ubing, tubing	(3) acidize wit	th 10,000 gallons ac	id,
(4) swab and test well and (5) run t	tubing, tubing	(3) acidize wit	th 10,000 gallons ac	id,
(4) swab and test well and (5) run t	tubing, tubing	(3) acidize wit	th 10,000 gallons ac	id,
(4) swab and test well and (5) run t	tubing,	(3) acidize wit	th 10,000 gallons ac	id,
(4) swab and test well and (5) run t	tubing,	(3) acidize wit	th 10,000 gallons ac	id,
(4) swab and test well and (5) run t	tubing,	(3) acidize wit	th 10,000 gallons ac	id,
(4) swab and test well and (5) run t	tubing,	(3) acidize wit	th 10,000 gallons ac	id,
(4) swab and test well and (5) run t	tubing,	(3) acidize wit	th 10,000 gallons ac	id,
(4) swab and test well and (5) run t	tubing,	(3) acidize with and place back	th 10,000 gallons acon production on Kob	id,
Approved	tubing	(3) acidize wit	th 10,000 gallons ac	id,
(4) swab and test well and (5) run t pump.	tubing	(3) acidize with and place back	th 10,000 gallons acon production on Kob	id,
Approved	tubing	(3) acidize with and place back	on production on Kob	id,
Approved	tubing	(3) acidize with and place back of the bac	on production on Kob Oil & Refining Compa on any or Operator ivision Superintende	id,
Approved	tubing	(3) acidize with and place back of the bac	on production on Kob Oil & Refining Compa on Pay or Operator ivision Superintende munications regarding well	id,
Approved except as follows:	tubing	Humble By Position Actg. D Send Com Name J. W. H	on production on Kob Oil & Refining Compa on Pay or Operator ivision Superintende munications regarding well	id,
Approved except as follows:	tubing	Humble By Position Actg. D Send Com Name J. W. H	on production on Kob Oil & Refining Compa Only or Operator Ivision Superintende munications regarding well ouse	id,