

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 87240
District II
811 South First, Artesia, NM 87210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised March 25, 1999

OIL CONSERVATION DIVISION
2040 South Pacheco
Santa Fe, NM 87505

WELL API NO. 30-025-02973
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. B-1576-3
7. Lease Name or Unit Agreement Name: VACUUM GB/SA UNIT EAST TRACT 3229
8. Well No. 002
9. Pool name or Wildcat VACUUM GRAYBURG/SAN ANDRES

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other	
2. Name of Operator Phillips Petroleum Company	
3. Address of Operator 4001 Penbrook Street Odessa, TX 79762	
4. Well Location Unit Letter <u>M</u> : <u>660</u> feet from the <u>SOUTH</u> line and <u>660</u> feet from the <u>WEST</u> line Section <u>32</u> Township <u>17S</u> Range <u>35E</u> NMPM County <u>LEA</u>	
10. Elevation (Show whether DR, RKB, RT, GR, etc.) 4000' RKB	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: DRILL A 1150' LATERAL ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

4/02/02 - SAFETY MTG. MIRU DDU (POOL WS #587) KILL WELL. POOH LAYING DOWN RODS AND PUMP. SI WELL. SD.
4/03/02 - SAFETY MTG. KILL WELL. ND WELLHEAD. NU BOP. POOH W/ 2-7/8" TBG. WINDY CONDITIONS. SHUT WELL IN. SHUT DOWN.
4/04/02 - SAFETY MTG. KILL WELL. FINISH POOH W/ 2-7/8" TBG. LAY DOWN 17 JTS 2-3/8" TBG. GIH W/ BIT, 5-1/2" SCRAPER & 2-7/8" TBG TO 3956'. POOH W/ 2-7/8" TBG, SCRAPER & BIT. GIH W/ 5-1/2" 3-L RBP, 5-1/2" RTTS PKR & 2-7/8" TBG. SET DOWN RBP @ 3936'. UNLATCH FROM RBP. LAY 1 JT 2-7/8" TBG DOWN. SET RTTS PKR @ 3905'. RU PUMP TRK TO TBG & TEST RBP TO 1000 PSI, HELD GOOD. RU PUMP TRK TO CSG. TEST TO 1000 PSI, HELD GOOD. RD PUMP TRK. UNSET PKR & GIH W/ 1 JT 2-7/8" TBG. LATCH ON TO RBP. UNSET RBP. POOH W/ 2-7/8" TBG, RTTS PKR & 3-L RBP, LAYING TBG DOWN.
4/05/02 - SAFETY MTG. MI RU HES WIRELINE TRK. TRK BROKE DOWN. RDMO HES WIRELINE TRK. WAIT ON ROTARY WIRELINE. MIRU ROTARY WIRELINE. GIH W/ GAUGE RING & COLLAR LOCATOR. LOCATE COLLARS. POOH W/ GAUGE RING & COLLAR LOCATOR. GIH W/ 5-1/2" EZ DRILL BRIDGE PLUG & COLLAR LOCATOR. SET 5-1/2" EZ DRILL BRIDGE PLUG @ 3926'. POOH W/ COLLAR LOCATOR. RDMO ROTARY WIRELINE. GIH PICKING UP WINDOW MILL/WATERMELON MILL

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Paul F. Kautz TITLE Supervisor, Regulation/Pror. DATE 5/09/02

Type or print name L. M. Sanders

(This space for State use)

ORIGINAL SIGNED BY Telephone No. 915-368-1488

PAUL F. KAUTZ
PETROLEUM ENGINEER

APPROVED BY _____ TITLE _____ DATE 5/18/02
Conditions of approval, if any: