

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-03001
5. Indicate Type of Lease STATE ☒ FEE ☐
6. State Oil & Gas Lease No. B-2519
7. Lease Name or Unit Agreement Name East Vacuum Gb/SA Unit Tract 3467
8. Well No. 027
9. Pool name or Wildcat Vacuum Gb/SA

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER ☐	
2. Name of Operator Phillips Petroleum Company	
3. Address of Operator 4001 Penbrook Street, Odessa, Texas 79762	
4. Well Location Unit Letter <u>G</u> : <u>1980</u> Feet From The <u>North</u> Line and <u>1980</u> Feet From The <u>East</u> Line Section <u>34</u> Township <u>17-S</u> Range <u>35-E</u> NMPM <u>Lea</u> County <u></u>	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3939' RKB	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐	REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐	ALTERING CASING ☐
PULL OR ALTER CASING ☐	COMMENCE DRILLING OPNS. ☐
OTHER: ☐	PLUG AND ABANDONMENT ☐
	CASING TEST AND CEMENT JOB ☐
	OTHER: <u>Reactivate</u> ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

10-17-90: R/U DDU. N/U BOP.
10-18-90: Wash and ream from 4555' to 4573'. Drill on junk from 4573' to 4574'.
10-19-90: Mill on junk from 4574' to 4575'.
10-20-90: Drill hard cement from 4578' to 4580'.
10-21-90: Drill cement from 4580' to 4602'.
10-22-90: Run GR/CNL Log and perforate as follows: 4536-4543'; 4545-4549';
4551-4555'; 4561-4565'; 4570-4574'; 4583-4588'
10-23-90: Stimulate well w/4268 gal of 15% NEFe HCl containing clay stabiliser &
LST agent and pump 1000 lb rock salt in gelled brine. Max pressure
3000 psi, avg 2500 psi, avg rate 2.6 bbl/min, ISIP 2150 psi.
10-24-90: Swab.
11-1-90: Pump 24 hr. 4 oil, 401 water, 0.5 mcf gas 6.7% CO2. Complete. Drop
From Report

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE L. M. Sanders TITLE Reg. & Proration Supv. DATE 11-5-90
TYPE OR PRINT NAME L. M. Sanders TELEPHONE NO. 915-368-1488

(This space for State Use)

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY: