

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-03013
5. Indicate Type of Lease	STATE ☒ FEE ☐
6. State Oil & Gas Lease No.	B-1845
7. Lease Name or Unit Agreement Name	Vacuum Abo Unit Btry 3 Tract 10
8. Well No.	7
9. Pool name or Wildcat	Vacuum Abo Reef

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

OIL
WELL ☒

GAS
WELL ☐

OTHER ☐

2. Name of Operator

Phillips Petroleum Company

3. Address of Operator

4001 Penbrook St., Odessa, Texas 79762

4. Well Location

Unit Letter K : 1980 Feet From The South Line and 1650 Feet From The West Line

Section 34

Township 17-S

Range 35-E

NMPM Lea

County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

3934' RKB; 3921' GL

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

10/27/92 MIRU DDU. ND wellhead & install BOP. GIH w/2-3/8 tbg @ 8475'.

10/28/92 Spot plug #1 25 sks class C neat 8475'-8375'. POOH to 6182'.

Spot plug #2 25 sks class C neat 6182'-6082'. POOH to 5534'.

Spot plug #3 60 sks class C neat 5534'-5136'. POOH to 3848'.

Spot plug #4 15 sks class C neat 3848'-3748'. POOH to 3148'.

Spot plug #5 15 sks class C neat 3148'-3048'. POOH w/2-3/8 tbg to ND BOP &

try to realease wellhead packing unable NU BOP.

10/29/92 RU Rotary WL & freepoint csg. Csg stuck 1238', RU & cut 5-1/2 csg 1150.

POOH & LD 35 jts 5-1/2 csg. GIH w/2-3/8 tbg & tag 1232. Couldn't get past 1232.

POOH & NU on wellhead & BOP & Close well in. Notified NMOC to spot lower plugs.

10/30/92 GIH w/6-3-1/2 DR & bit & drlg fill 1232 & wash & ream to 2964'. Circ hole

clean POOH. GIH w/2-3/8 to 2964' & spot plug #6 25 sks class C neat 2964'-

2864'. POOH & spot plug #7 25 sks class C neat 2428'- 2328'. POOH to 1606'.

Spot plug #8 25 sks class C neat 1606'-1506'. POOH to 1200' & spot plug #9

I hereby certify that the information above is true and complete to the best of my knowledge and belief. (Over)

SIGNATURE L. M. Sanders

TITLE Supervisor, Reg. Affairs DATE 11/4/92

TYPE OR PRINT NAME L. M. Sanders

TELEPHONE NO. 915/368-1488

(This space for State Use)

APPROVED BY [Signature]

TITLE

OIL & GAS INSPECTOR

DATE

DEC 14 '92

CONDITIONS OF APPROVAL, IF ANY:

10/31/92 40 sks class C neat 1200'-1100'. POOH w/2-3/8 tbg.
RU & perf squeeze hole 355' POOH & GIH w/pkr & establish injection
rate 2 BPM 300 PSI pump 250 sks class C neat. Circ 25 sks cnt. LD
pkp & cut off wellhead & install dry hole marker. RD DDU & cleaned
location.

RECEIVED

NOV 05 1992

OCD HOBBS OFFICE