

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

WATER CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.O.A.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. B-1482

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL <input type="checkbox"/> GAS <input type="checkbox"/> OTHER- Replug P&A Well	7. Unit Agreement Name SEVERAL
2. Name of Operator *Cities Service Oil Co.	8. Farm or Lease Name State BJ
3. Address of Operator Room 401, 4001 Penbrook Street, Odessa, Tx 79762	9. Well No. 2
4. Location of Well UNIT LETTER K, 2310 FEET FROM THE South LINE AND 1650 FEET FROM THE West LINE, SECTION 35 TOWNSHIP 17-S RANGE 35-E NMPM.	10. Field and Pool, or Wildcat Vacuum Abo Reef
11. Elevation (Show whether DF, RT, GR, etc.) 3917' DF	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	
* PPCo as Operator of East Vacuum <input checked="" type="checkbox"/> Grayburg-San Andres Unit re-entered, replugged per order R-5897.			

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

9-15-80 MI Well Units WS Unit. Drld surface plug to 60'.

9-16/18-80 CO from 60' to 4005'.

9-19/21/80 Ran 4-5/8" bit to 5002' COOH. Ran 2-7/8" tbg open end to 5000'. 9-21/22--crew off.

9-22-80 Spotted 200 sxs C1"C" cmt at 5015'. WOC 6 hrs. Tagged plug at 3898'.
Spotted 50 sxs C1"C" cmt at 3535'. WOC 15 hrs.

9-23-80 Tagged plug at 3545'. Spotted 100 sxs C1 "C" cmt at 3535'. WOC 6 hrs, tagged plug at 3178'. Spotted 50 sxs C1"C" at 2925'; 50 sxs at 1880', and 50 sxs at 360'. Circd from 120' to surface with 35 sxs. MO Well Units. Well P&A

9-23-80.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED W. J. Mueller TITLE Sr. Engineering Specialist DATE September 25, 1980

APPROVED BY Eddie TITLE DATE

CONDITIONS OF APPROVAL, IF ANY:

brb