

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

OIL CONSERVATION DIVISION

P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

WELL API NO.	30-025-03029
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	B-1482
7. Lease Name or Unit Agreement Name	STATE BJ
8. Well No.	1
9. Pool name or Wildcat	VACUUM

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator ME-TEX OIL & GAS, INC.	3. Address of Operator P.O. BOX 2070 HOBBS, NM 88240	4. Well Location Unit Letter M : 990 Feet From The SOUTH Line and 330 Feet From The WEST Line Section 35 Township 17-S Range 35-E NMPM LEA County
10. Elevation (Show whether DF, RKB, RT, GR, etc.)			

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data  
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER: <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER: <input type="checkbox"/>

SUBSEQUENT REPORT OF:

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.


REMEDIAL WORK:

PERFORATED YATES INTERVAL 3111' to 3354', ACIDIZED W/8000 GALS. USING BALL SEALERS IN 3 STAGES WITH NO SHOW OIL OR GAS.

PLUG AND ABANDON:

- 1) DISPL. CASING W/HVY LADENED MUD.
- 2) SET 35 SX CMT. PLUG 3080' ABOVE YATES PERFS & TAG.
- 3) SET 35 SX CMT. PLUG 280-380 PROTECT WTR SANDS & TAG.
- 4) SET 10 SX CMT. PLUG WITH MARKER AT SURFACE.
- 5) CUT ANCHORS CLEAN LOCATION (JUNK FROM PRIOR OPERATOR NOT HAULED OFF)

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE  TITLE PRESIDENT DATE 9/25/96  
TYPE OR PRINT NAME BURTON VETETO TELEPHONE NO. 505-397-7750

(This space for State Use)

APPROVED BY \_\_\_\_\_ DATE \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY: \_\_\_\_\_

SEP 30 1996