

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO.
1. Type of Well: OIL WELL ☐ GAS WELL ☐ OTHER <u>BRINE</u>		5. Indicate Type of Lease STATE ☒ FEE ☐
2. Name of Operator <u>UNICHEM INTERNATIONAL</u>		6. State Oil & Gas Lease No. <u>M-14244</u>
3. Address of Operator <u>P.O. Box 1499 HOBBS N.M. 88241</u>		7. Lease Name or Unit Agreement Name <u>TRUCKER I</u>
4. Well Location Unit Letter <u>A</u> : <u>660</u> Feet From The <u>NORTH</u> Line and <u>660</u> Feet From The <u>EAST</u> Line Section <u>1</u> Township <u>19 S</u> Range <u>35 E</u> NMPM <u>LEA</u> County		8. Well No. <u>1</u>
10. Elevation (Show whether DF, RKB, RT, GR, etc.)		9. Pool name or Wildcat <u>- NA -</u>

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☒
PULL OR ALTER CASING ☐		CASING TEST AND CEMENT JOB ☐	
OTHER: ☐		OTHER: ☐	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

SEE REVERSE SIDE

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

TITLE

HOBBS MANAGER

DATE

1-10-91

TYPE OR PRINT NAME

Pete M. Turner

TELEPHONE NO.

397-4994

(This space for State Use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

ROWLAND TRUCKING COMPANY

A DIVISION OF
EUNICE RENTAL TOOL COMPANY

418 SOUTH GRIMES

HOBBS, NEW MEXICO 88240

ROWLAND TRUCKING CO.

TRUCKERS 1

418 SOUTH GRIMES

HOBBS, NEW MEXICO 88240

ROWLAND TRUCKING CO.

TRUCKERS 1

PHONE
[505] 393-9023

PHONE

12/14/90

PULLED 2 7/8 TUBING OUT OF WELL. PULLED 5 1/2 CASING AND LAY DOWN. RUN 8 5/8 PLUG INTO WELL. SET PLUG AT 1850. PULLED WIRE-

LINE OUT OF ROPE SOCKET.

12/15/90

FISH ROTARY WIRELINE TOOLS. PULL OUT OF WELL AND SHUT DOWN.

12/17/90

GO IN HOLE WITH TUBING AND TAG PLUG. PUMP 1ST CEMENT PLUG. LOST PARTIAL CIRCULATION WHILE PUMPING CEMENT. WAIT 3.5 HRS FOR CEMENT TO SET UP. WENT TO THE PLUG WITH TUBING. PULL OUT OF HOLE AND PUT ON 8 5/8 PACKER AND WENT BACK INTO HOLE WITH TUBING. COULD NOT GET PACKER TO SET. PULL OUT OF HOLE AND CHECK WELL HEAD AND CASING. CASING IS 9 5/8 NOT 8 5/8 SHUT DOWN.

12/18/90

RIG UP HALLIBURTON WIRE LINE AND RUN 8.15 GAGE RING WENT TO 1224. AND HIT CEMENT. PRESSURE UP ON PLUG WOULD NOT PRESSURE UP. PULL BACK OUT OF WELL AND LAY DOWN JOINTS OF TUBING. RUN 8 1/2 BIT AND SCRAPER ON TUBING. TO CIRCULATE LOOSE CEMENT OUT OF WELL. WENT INTO WELL WITH SCRAPER WASH CEMENT OUT OF THE HOLE AND GO BACK INTO HOLE WITH 8 5/8 PACKER. SET PACKER AND 1825. AND LOADED THE BACK SIDE AND TESTED TO 500 LBS HELD FOR 15 MIN.

12/19/90

PULL OUT OF THE HOLE WITH THE PACKER. RUN 9 5/8 PLUG TO 1826. AND SET. TESTED PLUG TO 500 LBS. GO IN THE HOLE WITH TUBING AND TAG PLUG. CIRCULATE WELL WITH FRESH WATER. START PUMPING CEMENT 1ST STAGE. PUMP 2ND STAGE OF CEMENT. PUMP 3RD STAGE OF CEMENT. CUT OFF WELL HEAD AND WELD ON DRY HOLE MARKER.