to Appropriate District Office	with gy, with a second with the	aller an affeir an her an	and the second		
DISTRICT	OT OF BEDVATION DIVISION		WEL INO.		
DISTRICT II Santa Fe, New Mexico 87504-2088			30-025-03218		
P.O. Drawer DD, Artesia, NM 88210			5. Indicate Type of Lease STATE FEE		
DISTRICT III 1000 Rio Brazos Rd., Aziec, NM 87410			6. State Oil & Gas Lease No.		
SUNDRY NOTICES AND REPORTS ON WELLS					
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"			7. Lease Name or Unit Agreement Name		
(FORM C-101) FOR SUCH PROPOSALS.)			- East Pearl Queen Unit		
1. Type of Well: OIL OAS			tuat feati Queen onit		
weit weit onter Injection			8 Well No.		
Pyramid Energy, Inc.			8. Well No. 25		
3. Address of Operator			9. Pool name or Wildcat		
10101 Reunion Place, Ste. 210 San Antonio, TX 78216 Pearl Queen 4 Well Location					
Unit Letter E : 1980 Feet From The North Line and 660 Feet From The West Line					
Section 27	Township 195 Ra	nge 35E	NMPM Lea County		
	10. Elevation (Show whether	DF, RKB, RT, GR, etc.)			
3735 DF					
11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:					
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:					
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT					
PULL OR ALTER CASING CASING TEST AND C					
OTHER:	·	OTHER:			
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed					
work) SEE RULE 1103.					
06/06/94 Tagged bridge plug at 4550° and circulated hole with mud. Spotted 25 sacks					
of cement on top of plug. Located holes from 2800' to 3360'. Obtained plugging instructions from NMOCD. Spotted 75 sacks of cement at 3360' and squeezed holes. Tagged cement inside casing with wireline at 2664'. Perforate casing 4 shots at 345'. Pumped down casing through perfs and			m 2800' to 3360'. Obtained		
			circulated 110 sacks of cement from 345' back to surface between 8 5/8" and		
			5 1/2" casings. Left cement inside 5 1/2" casing from surface to 345'. Cut		
off wellhead 3' below ground level and welded on cap and marker. Well plugged					
	and abandoned.				
		:			
I hereby certify that the information above is true and complete to the best of my knowledge and belief.					
I hereby certify that the in	principal above is true and complete to the best of my knowledge an		ns Manager 06/20/94		
SIGNATURE	Nut		DATE		
TYTE OR PRINT NAME	Scott Graef		<u>телетноже мо. (210) 308-</u> 800		
(This space for State Use)	$\sim \sim 1.1$	CIL & GAS	PROVENTION PROVENTION		
	I we we hid		AJO 31 1013		
ANTROVED BY	wing purint in	m.e	DATE		
CONDITIONS OF AFTROVAL, IF ANY:					

CB

(j) do