NO. OF COPIES RECEIVED		
DISTRIBUTION		Form C-103
SANTA FE		Supersedes Old C-102 and C-103
FILE	NEW MEXICO OIL CONSERVATION COMMISSION	Effective 1-1-65
U.S.G.S.	AUG 11 10 20 113 '69	
LAND OFFICE		5a. Indicate Type of Lease
OPERATOR		State X Fee
		5. State Oil & Gas Lease No.
SUNDO		B-2359
(DO NOT USE THIS FORM FOR PROF USE "APPLICATION		
1.	Y NOTICES AND REPORTS ON WELLS POSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. ON FOR PERMIT " (FORM C-101) FOR SUCH PROPOSALS.)	Ω[]]]]]]]]]]]]]]]]]]]]]]]]]]]]]]]]
OIL GAS WELL		7. Unit Agreement Name
2. Name of Operator	OTHER-	Lovington San Andres Uni
Skalle A		8. Farm or Lease Name
3. Address of Operator	11 Company	
		9. Well No.
4. Location of Well	x 730 - Hobbs, New Mexico	47
		10. Field and Pool, or Wildcat
UNIT LETTER K, 19	80 FEET FROM THE South LINE AND 1980 FEET I	
		ROM Lovington San Andres
THE West LINE, SECTION	1 TOWNSHIP 175 RANGE 36E	
		лем. <u>()                                   </u>
	12. County	
	15. Elevation (Show whether DF, RT, GR, etc.) 3836' D.F.	
Check Ar	DEFORTIATE BOX To Indiana No.	Les ALIIIII
NOTICE OF INT	propriate Box To Indicate Nature of Notice, Report or	Other Data
	SUBSEQUE	ENT REPORT OF:
PERFORM REMEDIAL WORK		
EMPORARILY ABANDON	PLUG AND ABANDON	ALTERING CASING
ULL OR ALTER CASING	COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
	CHANGE PLANS CASING TEST AND CEMENT JOB	
OTHER	OTHER Converted to	Injection
7. Describe Proposed or Completed Opera	tions (Clearly state 1)	

2. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 1. Pulled rods and tubing.
- 2. Cleaned out to 4935'.

int.

.

- 3. Ran internally coated (Duo-line) 2-3/8" OD tubing with Halliburton Tension Type R-3 Packer set at 4517' with 13,000#.
- 4. Filled casing annulus behind tubing with treated water.
- 5. Well converted to injection status 10:00 a.m. August 6, 1969.
- 6. Injection will be into open hole 4620-4935'. T.D. 4944'.
- 7. Hooked up to injection system.

Work approved by Commission Order No. WFX-319.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED (ALPHOR) V. St. PLANCHAR	TITLE District Production Manager	DATE August 8, 1969
V. E. Pletcher	TITLE	DATE

NO. OF COPIES RECEIVED		Form C-103
DISTRIBUTION		Supersedes Old C+102 and C-103
SANTAFE	NEW MEXICO OIL CONSERVATION COMMISSION	Effective 1-1-65
FILE		
U.S.G.S.		5a. Indicate Type of Lease
LAND OFFICE		State 🗶 🛛 🛛 Fee
OPERATOR		5. State Oil & Gas Lease Nc.
······································		B-2359
SUNDRY (DO NOT USE THIS FORM FOR PROP USE "APPLICATIC	NOTICES AND REPORTS ON WELLS OSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVO IN FOR PERMIT -** (FORM C-101) FOR SUCH PROPOSALS.)	
1.		7. Unit Agreement Name
OIL GAS WELL	OTHER.	Lovington San Andres Uni
2. Name of Operator		8. Farm or Lease Name
Skelly Oil Company		
3. Address of Operator		9. Well No.
P. O. Box 730 - Hobbs,	New Mexico 88240	47
4. Location of Well		10. Field and Pool, or Wildc at
UNIT LETTER	1000 1000	
UNIT LETTER,	80 FEET FROM THE SOUTH LINE AND 1980	FEET FROM Lovington Sen Andres
	1 170 0/-	
THE WEST LINE, SECTION	1 TOWNSHIP 178 RANGE 36E	<u> — ммрм. () () () () () () () () () () () () () </u>
	15. Elevation (Show whether DF, RT, GR, etc.)	12. County
	3836' DF	
<sup>16.</sup> Check A	ppropriate Box To Indicate Nature of Notice, Rep	ort or Other Data
NOTICE OF INT		SEQUENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON	ALTERING CASING
PULL OR ALTER CASING	COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
	CHANGE PLANS CASING TEST AND CEMENT JO	
	OTHER STATES	
OTHER		
17 Describe Proposed or Completed One	rations (Clearly state all pertinent details, and give pertinent dates	
work) SEE RULE 1 f03.	autons (Greanty state all pertinent actalls, and give pertinent dates	s, including estimated date of starting any proposed

Moved in and rigged up workover rig 10-8-68. Dumped 21 gallons Hydromite 4912-4905'. Dumped 21 gallons Hydromite at 4905' - Found top of Hydromite at 4800'. Drilled Hydromite with sand pump 4800-4805'; then found top of Hydromite at 4905'. Dumped 21 gallons Hydromite at 4648'. Rain tubing with 4-3/4" bit and drilled out Hydromite 4648' to 4668'. Carculated hole clean to 4905'. Dumped 21 gallons Hydromite 4817' to 4847' and circulated hole clean to 4905'. Pulled tubing and bit. Shut in for observation.

Rigged up workever rig 11-1-68. Ran tubing and Lynes operhole Infaktable packer to 3500'.

Squeezed openhele section 4880-4905' down tubing with 3,000 gallens "zone lock." Let "zone lock" set for 18 hours.

Lowered tubing and packer, tagged top of plug at 4888', pulled tubing and packer. Moved in workover rig 11-16-68. Ran 160 Jts. (4871') of 2-3/8"OD tubing and set at 4871', setting nipple at 4838', perforations 4838'-4841'. Ran rods with pump set at 4838'. Installed pumping equipment.

Well tested 11-24-68 producing no oil and 157 bbls. water per day through open hole section 4620-4888' from the San Andres Poel.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief. (ORIGINAL) Y. B. Fletcher SIGNED) Y. B. Fletcher					
SIGNED	TITLE District Production Manager	DATE 12-9-68			
APPROVED BY APPROVAL, IF ANY:	TITLE	DATE			