

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Benito Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.

30-025-03818

5. Indicate Type of Lease

STATE ☒

FEE ☐

6. State Oil & Gas Lease No.

E-2359

7. Lease Name or Unit Agreement Name

State LA

8. Well No.

10

9. Pool name or Wildcat

Lovington ABO

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

OIL WELL ☒

GAS WELL ☐

OTHER TA

2. Name of Operator

Amerada Hess Corporation

3. Address of Operator

Drawer D, Monument, New Mexico 88265

4. Well Location

Unit Letter H : 1650 Feet From The North Line and 660 Feet From The East Line

Section 1 Township 17S Range 36E NMPM Lea County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

3834' DF

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☒

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plan to MIRU pulling unit, remove well head, install BOP & TOH w/tbg. & pkr. TIH w/5-1/2" CIBP & set at + 8200'. Circ. hole clean. TIH w/perforating gun & shoot 2 holes at + 4900'. TIH w/5-1/2" pkr. to + 4800' & est. inj. rate into hole at 4900'. TOH w/pkr. TIH w/5-1/2" EZ drill retainer & set at + 4800'. Load & test tbg. to 2000# & csg. to 500#. Squeeze G/SA Zone as conditions warrant. WOC. Run temperature survey to locate cement top. Re-squeeze if necessary. TIH & circ. hole clean. Press. test csg. to 500# for 30 min. Obtain chart. Remove BOP, install well head, RDPU & clean location. Continue TA'd status.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

R. L. Wheeler, Jr.

TITLE

Supv. Adm. Svc.

DATE

4-29-92

TYPE OR PRINT NAME

R. L. Wheeler, Jr.

TELEPHONE NO.

393-2144

(This space for State Use)

Orig. Signed by
Paul Kautz
Geologist

APPROVED BY

TITLE

DATE

MAY 05 '92

CONDITIONS OF APPROVAL, IF ANY: