

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION 8 50
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.
30-025-03829

5. Indicate Type of Lease
STATE ☒ FEE ☐

6. State Oil & Gas Lease No.
N/A

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL ☐ GAS WELL ☐ OTHER Water Disposal

2. Name of Operator
Araho, Inc.

3. Address of Operator
P.O. Box 983, Hobbs, NM 88240

4. Well Location
Unit Letter I : 2190' Feet From The South Line and 560' Feet From The East Line

Section 1 Township 17S Range 36E NMPM Lea County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

3828' DF

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- MIRU PU. PU 4 5/8" bit on tbg and TIH. Tag TD @2346'. POOH. PU 6 1/8" lead block & TIH. TAG @1926'. POOH. Block impression indicates parted csg. TIH w/OE tbg. Stacked out @ 1926'. POOH.
- RU PMP trk. Pmp'd 50 bbl 10# brine. Well went on vacuum. RU & PMP 300 sx C1 "H" cmt. SIP = 30#.
- RU PMP trk. Pmp'd 50 bbl 10# brine. Well went on vacuum. RU & PMP 400 sx C1 "H" cmt w/2% CaCl. SIP = 65#.
- RU PMP trk. Pmp'd 50 bbl 10# brine. Well holding 60 Psig. POOH w/tbg.
- RIH to 1926' w/tbg. RU PMP trk. PMP 150 sx C1 "C" w/2% CaCl. POOH w/tbg. WOC 2 hrs. TIH, did not tag cmt. SION.
- RU PMP trk. PMP 75 sx C1 "C" cmt w/3% CaCl. POOH w/tbg. WOC 2 hrs. TIH w/tbg. Tag cmt @ 1823'. POOH w/tbg.
- MIRU WL. TIH w/perf gun. Perf w/4 Jspf @500'. POOH. RD WL. PU cmt. ret on tbg & TIH. Set Ret @ 390'. RU PMP trk. Circ 260sx thru 8 5/8" x 13 3/8" annulus. Cmt to surf. POOH.
- RIH w/1 jt tbg, circ cmt to surf. in 8 5/8" csg.
- Cutoff wellhead. Weld on marker. Clean location.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Dorothy Runnels TITLE President DATE 07-15-94

TYPE OR PRINT NAME Dorothy Runnels

TELEPHONE NO.

(This space for State Use)

APPROVED BY David Citaint TITLE Petroleum Engineer DATE 7/26/94

CONDITIONS OF APPROVAL, IF ANY: