## STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT

	*1- MU	1 1 (V) C
COPIES ACCEIVED	T	
DISTRIBUTION	1	1
SANTA FE	†	<del> </del>
FILE	†	<del> </del>
U.S.G.S.	†	
LAND OFFICE	<del>                                     </del>	<del> </del>

## OIL CONSERVATION DIVISION P. O. BOX 2088 SANTA FE, NEW MEXICO 87501

Form C-103 Revised 10-1

	U.S.G.S.	]	NIA FE, NE	W MEXICO 87501		Revis	ed 10-1
	LAND OFFICE		Separate in the second second	and the state of the state of		5a. Indicate Type of Lease	
	and the state of t					Suc X	
						Cherry Manager and Manager	to the time the training
	MEET TY	OTHER-				7. Unit Agreement Name	7777
i	ame of Operator					The state of the s	elet under die
3. A	exaco Producing Inc.					β. Farm or Lease Name	Un
						Lovington San A	ndres
7.6	Box 728, Hobbs, New					42	
- 1	UNIT LETTER F	1980		198	0	10. Field and Pool, or Wildo	
	2 2 4	FEET FROM	A THENorth	LINE AND3300	FFFY FRA	Lovington San Ar	
	THE Bast	1			- FEET FROM		TTTT
keer	LINE, SECTION	'	OWNSHIP 17;	S RANGE 36E	NMPM.		
				DF, RT, GR, etc.)			
16.		<u>////</u> / 3840	)' DF			12. County	1111
	Check A	ppropriate Box	To Indicate ?	Nature of Notice, Repo	<u>-</u>	Lea	77777
	NOTICE OF INT	ENTION TO:	- I	l sup	ort or Othe	er Data	
PERF	RM REMEDIAL WORK			300.	PEQUENT	REPORT OF:	
	PARILY ASANDON	PLUG	AND ABANDON	REMEDIAL WORK	X	<b>A</b> 1 mm - 1	_
	DR ALTER CASING			COMMERCE DRILLING OPNS.		ALTERING CASING PLUG AND ABANDONN	
	. 🚅	CHANG	E PLANS	CASING TEST AND CEMENT JO	_ م	- TOU ABANDONL	IENT _
011	ER			OTHER			Γ.
17. De	scribe Proposed or Completed O-						
wpi	scribe Proposed or Completed Operator (k) SEE RULE 1103.	mons (Clearly state	all pertinent deta	ils, and give pertinent dates,	including es	timated date of starting	
						of starting any p	roposed
1)	MIRU 7/25/87. Pull	rods and num	nn Tnatai	1 70-			
2)				BOP. Pull tubin	g.		
2)	Clean out junk and f	ill 4838'-49	39'.				
3)	Set 7" packor at 450						
,	Set 7" packer at 450 15% NEFE with 2 drum	Acidize	6 1/4" OH	4536'-4939' with	4000 gal	lone	
	15% NEFE with 2 drum balls between stages	s recalax in	2 stages w	ith 500# rocksalt	and 500	# moth	
4.)	SI 2 hours. Flowbac in 24 BFW. Flush wi	k load and	109 BFW. p	imp 2 drume apaca			
	in 24 BFW. Flush wi	th 400 Bbls.	SI 78 hou	rs.	scale in	hibitor	
5).	Run production equip						
•	brodde etci ednibi	ment.		•			
10 11				•			
10. I here	by certify that the information above	t is true and comple	te to the best of n	y knowledge and belief.			
	la bla			<u> </u>	397	<del>-</del> 3571	
\$16HED	Julyan -		TITLE Hobbs	Area Superintend	Bent	λυσ ε 3000	
	ORIGINAL SIGNED BY JERK	V comme		1 A. Celic		Aug. 6, 1987	
APPROVED	DISTRICT I SUPERVIS	T SEXTON				All 1 1 1003	
CONDITIO	NE OF APPROVAL, IF ANY:		TITLE			AUE 1 1 1987	
	TOTAL, IF ANY:				`		