

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

**OIL CONSERVATION DIVISION**  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-03843

5. Indicate Type of Lease  
STATE ☒ FEE ☐

6. State Oil & Gas Lease No.

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:  
OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. Name of Operator  
PENROC OIL CORPORATION

3. Address of Operator  
P.O. Box 5970, HOBBS, NM 88241-5970

4. Well Location  
Unit Letter E : 1650 Feet From The NORTH Line and 990 Feet From The West Line  
Section 1 Township 17 S Range 36 E NMPM 65A County

7. Lease Name or Unit Agreement Name

STATE E TRACT 18

8. Well No. 19

9. Pool name or Wildcat  
Lovington Aho

10. Elevation (Show whether DF, RKB, RT, GR, etc.)  
3844' RDB

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

**NOTICE OF INTENTION TO:**

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐  
OTHER: ☐

**SUBSEQUENT REPORT OF:**

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒  
CASING TEST AND CEMENT JOB ☐  
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

2.21.92 - 2.29.92 : RU # pulled rods & pump. Attempts to pull tbg failed. Run free point - tagged @ 7845'. Backed off tbg @ 7816'. Ram pkr & swab tested well - swabbed down. After discussion w/ NMOC & Greenhill, decided to P&A'. Ram & set retainer @ 7766' and pumped 100 sxs. Pulled out of retainer. Circulated hole w/ gelled brine. TDH w/ tbg. Perf. 2 holes each @ 5975' and 4450'. TIH w/ HOWCO retainer, & set @ 5844'. Pumped 50 sxs. of cement. LD tubing, TIH w/ another ret. & set @ 4329'. Pumped 50 sxs. LD tbg to 1906'. Set 50 sxs. cmt plug. Pull up & set 50 sxs. plug @ 316', & 20 sxs. @ surface. Cut off well head, install dry hole marker, cut off deadman. Cleaned up loc. Ready for inspect.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE M. Y. (Merch) Merchant TITLE PRESIDENT DATE 2/29/92  
TYPE OR PRINT NAME M. Y. (Merch) Merchant TELEPHONE NO. 505-397-3596

(This space for State Use)

APPROVED BY Chandler TITLE OIL & GAS DIVISION DATE

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

MAR 02 1992

DCD HOBBS OFFICE