

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.O.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

5a. Indicate Type of Lease
State ☒ Free ☐

5. State Oil & Gas Lease No.

B-1553

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator AMOCO PRODUCTION COMPANY	8. Farm or Lease Name State E Tract 18
3. Address of Operator P. O. Box 68, Hobbs, NM 88240	9. Well No. 20
4. Location of Well UNIT LETTER H 1650 FEET FROM THE North LINE AND 330 FEET FROM THE East LINE, SECTION 2 TOWNSHIP 17-S RANGE 36-E NMPM.	10. Field and Pool, or Wildcat Lovington Abo
15. Elevation (Show whether DF, RT, GR, etc.) 3838' RDB	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Propose to plug and abandon subject well as follows: (Notify NMOCD 24 hours before starting work.)
Pull tubing. Set a cast iron bridge plug at 8200' and cap with 35' class C neat cement. Spot 41 sacks class C neat cement 4900'-4650'. Spot 25 sacks class C neat cement across top of Yates (3075'-2925'). Spot 25 sacks class C neat cement across top of Salt (2175'-2025'). Spot 15 sacks class C neat cement at surface. Erect PXA marker and cap well. (Note: place mud consisting of 10# brine and 25# gel/bbl between all plugs).

O+5-NMOCD, H 1-R. E. Ogden, HOU Rm. 21.150 1-F. J. Nash, HOU Rm. 4.206 1-CLF 1-GDH, bldg.

THE COMPLETION OF THIS NOTICE 24 HOURS BEFORE THE BEGINNING OF PLUGGING OPERATIONS FOR THE WELL TO BE ABANDONED.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Cathy L. Forman TITLE Assist. Admin. Analyst DATE 3-8-84

ORIGINAL SIGNED BY JERRY SEXTON

APPROVED BY DISTRICT I SUPERVISOR

TITLE

DATE MAR 12 1984

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED
MAR 9 1984
O.C.
HODGINS