STATE OF NEW MEXICO ERGY AND MINERALS DEPARTMENT

MA. OF COPIES ACCEIVES	T	
DISTRIBUTION		
BANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NO. OF COPIES RECEIVES	OIL CONSERVA	TION DIVISION	
DISTRIBUTION	ISTRIBUTION P. O. BOX 2088		Form C-103 Revised 19-1-78
SANTA FE	SANTA FE, NEW MEXICO 87501		KEA1260 10-1-19
FILE			5a. Indicate Type of Lease
U.S.G.S.			[]
LAND OFFICE			
OPERATOR			5. State Oil & Gas Lease No.
CUALIS	V NOTICES AND DEPORTS ON	WELLS	
IDO NOT USE THIS FORM FOR PRO	Y NOTICES AND REPORTS ON POSALS TO DRILL ON TO DEEPEN OF PLUG B	ACK TO A DIFFERENT RESERVOIR.	
USE "APPLICATI	ION FOR PERMIT -" (FORM C-101) FOR SUC	H PROPOSALS.)	7. Unit Agreement Name
O(L			7. Ohit Agreement Name
WELL OTHER- Water Injection			West Lovington Unit
Name of Operator			8. Farm or Lease Name
			West Lovington Wnit
TEXACO INC. Address of Operator			9. Well No.
P. O. Box 728, Hobbs, New Mexico 88240			6
Location of well			Lovington San
UNIT LETTER B . 660 FEET FROM THE NOTTH LINE AND 1980 FEET FROM			Andrea West
UNIT CETTER C	FEET FROM THE		
_ ,	17_9	36-E	
THE FAST LINE, SECTION	DN 4 TOWNSHIP 17-S	RANGEN	COM. (
mmmm		DE PT CP and	12. County
	15. Elevation (Show whether	Dr. RI, GR, etc.)	12. Comny
		<u> 3899' (GR)</u>	Lea
16. Check	Appropriate Box To Indicate N	lature of Notice Report of	Other Data
	•• •	-	
NOTICE OF IN	ITENTION TO:	SUBSEQUE	ENT REPORT OF:
		<u> </u>	
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING
TEMPORARILY ADANDON		COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
PULL OR ALTER CABING	CHANGE PLANS	CASING TEST AND CEMENT JOB	
Poet on Action Capino		OTHER Repair Casin	x Leak
		1.01.22.	
OTHER			
The Completed Or	perations (Clearly state all pertinent det	nils and give pertinent dates, inclu	ding estimated date of starting any proposed
work) SEE RULE 1103.	Selucions (Crearly State are pertinent den	arts, and give pertinent dates, there	and commerce and of ordering any property
• •			
	•		
T Dimmi um T	install BOP. Pull tubing	and nkr.	
1. Rigged up. 1	install bor. Full cubing	on plus (ppm) 1650!)	
	90' and spot 40' cement	ou bind (FPID 40)0).	
3. Set pkr @ 459	O'. Casing leak below p	kr.	
4. Set CIBP @ 45	500' and spot 40' cement	on plug (PBTD 4460').	
5. Hang one join	nt bubing and load hole W	/inhibited water.	
6. Well shut-in,	7-10-8h	,	
O. WELL BRUC-IN,	, 1-19-01.		
		•	
		-	
	,		
			_
18 I hereby certify that the information	above is true and complete to the best	of my knowledge and belief.	
/ / /		. •	
			يست من
DIGHED ////	TITLE A	st. Dist. Mgr.	DATE 7-26-84
onest wor	,1960年6月 1 提 相信件		THE STORES
# 2 - 12 - 12 - 12 - 12 - 12 - 12 - 12 -	. 1.00 % 0		JUL 27 1984