Form SG104

LW MEXICO STATE LAND OFFICE SANTA FE, NEW MEXICO DEPARTMENT OF THE STATE GEOLOGIST SANTA FE

NOTICE OF INTENTION TO ABANDON WELL

Notice must be given at least five days before work is to begin to the State Geologist or to the proper Oil and Gas Inspector. It is desirable that a representative of the Department of the State Geologist witness the plugging of wells being abandoned whenever possible. If changes in the proposed plan are considered advisable, a copy of this notice showing such changes will be returned to the sender. Submit this notice in duplicate.

The reasons for wishing to abandon the well are as follows:

Drilled to 5216 feet, which is considered test in this area. Well is a dry hole.

The present condition of the well is as follows:

212' - 15¹" Casing in hole 1658'7" - 10^H " " " 3490'8" - 5¹₄" " " " Depth 5216 feet. Abount 3000 feet water in hole.

The work which we propose to do in abandoning the well is as follows:

Will fill hole with heavy mud to 4950 and set 5 sacks cement. After pulling casing will fill hole with heavy mud. Surface water is comented and cased off with $15\frac{1}{2}$ " casing. The casing at this water point will be left in hole.

Sincerely yours,

Approved	Western Drilling & Engineering Co.
DUPLICATE	By Bec y.
	Send communications regarding this well to
State Geologist or Oil and Gas Inspector.	Address AFtesia, New Mexico.