

New Mexico X State
Page two

Cont w/ 5½ RDB & 2-7/8 WS to 9062. Howco spot 84 gal 15% NEFEHCL 9062-8978. Raise and set RDB 8880. Load csg attempt to trap 500 would not hold. Raise to 8848 would not hold. POH. RIH w/ new 5½ RDB & 2-7/8 to 8880.

Howco trap 500# on csg. Acdz perfs 8983-9062 w/ 5000 gal 15% NEFEHCL in 4 equal stages.

3½ hr. Swab, Tr oil. POH Go perf 8919-95 (37 holes) w/ 4" csg gun, 23 gram.

Howco dump Bailer PB w/ SD 9044-9000 RIH w/ 5½ RDG & 2-7/8 to 7000'.

Lower Pkr to 8995 Howco spot 2 bbl 15% NEFE 8995-8911. Raise & set RDG @ 8785 Howco trap 500# on csg. Howco acdz perfs 8919-8995 w/ 4000 gal 15% NEFE w/ 55 RCNBS. Max 2600 Min 800 Avg 2000 Final 2600
6½ hr swab, 0 B0

2 hrs swab no oil, POH w/ tbg and pkr/ Ran hydrostatic bailer on 2-7/8 tbg, CO 9000-9190 PBD, POH and recover sand and salt and scale.

RIH w/ 2-3/8 & 2-7/8 tapered Prod. setup TS 9175, SN 9138

RIH w/ 1¼ pump on rods.

24 hrs, P, 14 B0, 36BW, 8 x 100 x 1¼ NFL