

STANDARD STATE #1

Page #3

- 7/28/77 Went in hole w/wash pipe w/large ID shoe. Milled overbit and dropped down 10' to retainer. POH w/wash pipe, picked up overshot. Went picked up fish and POH w/fish. Started back in w/bit.
- 7/29/77 Drilled out retainer and cement, cleaned out down to 4827'. POH
- 7/30/77 Reperforated zone 4895-4905. Went in hole w/RTTS Set RTTS @ 4800'. Swabbed well dry.
- 8/1/77 Fluid level 2500' no oil. Treated well w/1000 gal acid. Saw tooth water ahead of acid in using 2500# as upper limit, well went a vacuum when acid hit formation. After swabbing back acid water, started swabbing formation water.
- 8/2/77 Fluid level 1800', no oil. Sqzd off zone using 100 sx Class C. Well sqzd off w/40 sx in zone, 4000#. Reversed out and POH.
- 8/3/77 Went in hole w/bit, drilled out 60' cmt down to 4885'. Spotted 1000 gals acid, POH. Perforated well 4818-28 4840-50, 20 holes. Went in hole set pkr @ 3600', fluid level 2000', pump 1000 gals of water. Moved pkr down to 4800' started to swab. Swabbed fluid down to 3000'.
- 8/4/77 Fluid level 1800, swabbed down to 3000, formation water.
- 8/8/77 POH w/pkr, went back in open ended and set a 20 sx plug across perforations. Tag plug w/wireline, 4720'. Circulated hole w/salt gel. POH. Rigged up to pull casing.
- 8/9/77 Shot 5½" casing @ 4400', pulled and laid casing. Went back in and set plugs @ casing stub-4420 and base of 8 5/8".
- 8/10/77 Set plug above salt, and surface plug w/marker. Rigged down.

RECEIVED
MAY 5 1980
OIL CONSERVATION DIV.