

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

106 7 35 AM '68

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
00 950	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Dry Hole - Temp. Abandoned		7. Unit Agreement Name
2. Name of Operator Standard Oil Company of Texas - A Division of Chevron Oil Company		8. Farm or Lease Name Kelly State 30
3. Address of Operator 3610 Avenue S - Snyder, Texas 79549		9. Well No. 1
4. Location of Well UNIT LETTER D , 625 FEET FROM THE W LINE AND 660 FEET FROM THE N LINE, SECTION 30 TOWNSHIP 17S RANGE 36E NMPM.		10. Field and Pool, or Wildcat Undesignated
15. Elevation (Show whether DF, RT, GR, etc.) GL 3890'		12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

P&A PROCEDURE

1. Run tubing. Spot 25 sack cement plugs as follows:

- (a) 8900'
- (b) 7100'
- (c) 6200'
- (d) 4900'
- (e) 4100' (Base of 8-5/8" @ 4117')
- (f) Surface of 8-5/8"

2. Cut off casing, weld on cap, set marker. Level location. Work to commence when approved.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED B. Davidson TITLE District Drilling Supervisor DATE 8-5-68

APPROVED BY John W. Remy TITLE Geologist DATE AUG 7 1968

CONDITIONS OF APPROVAL, IF ANY: