STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT

. NO. O' COPIES ACCEIVED		
DISTRIBUTION		
SANTA FE		
FILE	<u> </u>	
U.S.G.S.		
LAND OFFICE		
OPERATOR		

DISTRICT | SUPERVISOR

CONDITIONS OF APPROVAL, IF ANY:

.L CONSERVATION DIVISION

DISTRIBUTION	P. O. BOX 20	88	Revised 10-1-78
SANTA PE	SANTA FE, NEW ME	EXICO 87501	
FILE	4		5a. Indicate Type of Lease
U.S.O.S.	4		State Fee X
OPERATOR	1		5. State Oil & Gas Lease No.
SUNDE	Y NOTICES AND REPORTS ON WEL	LLS	
(DO NOT USE THIS FORM FOR PRI USE "APPLICAT	RY NOTICES AND REPORTS ON WELD OPEN AND REPORTS ON WELD OPEN AND REPORTS OF PLUG BACK TO THE PORT OF PERMIT - " (FORM C-101) FOR SUCH PRO	O A DIFFERENT RESERVOIR.	
			7. Unit Agreement Name
WELL X WELL	OTHER-		
ame of Operator			8. Farm or Lease Name
Sun Exploration & Pr	oduction Company		Caylor, C.S. Sr. Estat
dress of Operator			9. Well No.
P.O. Box 1861 Mi	dland, Texas 79702		
ocation of Well	cco Nouth	665	10. Field and Root, or Wildcat Loving Abo
D	660 North North	INE AND FEET FROM	
THE West LINE, SECT	on 6 TOWNSHIP 175	RANGE 37E NMPM.	
HHHHHHHH	15. Elevation (Show whether DF,	KT, GR, etc.)	12. County
	VIIII		Lea Allilli
Check	Appropriate Box To Indicate Natu	re of Notice, Report or Oth	ner Data
	NTENTION TO:		REPORT OF:
·			_
ORM REMEDIAL WORK	PLUG AND ABANDON RE	MEDIAL WORK	ALTERING CASING
PORARILY ABANDON	co	MMENCE DRILLING OPHS.	PLUG AND ABANDONMENT
OR ALTER CABING	CHANGE PLANS CA	SING TEST AND CEMENT JOB	_
	_	OTHER	L
THER			
			and data of starting any propose
escribe Proposed or Completed Coprk) SEE RULE 1103.	perations (Clearly state all pertinent details,	and give pertinent dates, including	estimated date of starting any propose
· •	POUL /2 2 / 0 II / 1 7 # 1 FF p	and the & Pode submers	ible equip Have numn
1. MIRU PU. NU BOP.	POH w/2-3/8", 4.7#, J-55 p Reda facilities (Midland):	Motors to be tested	cleaned & rerun.
& motors sent to	Reda facilities (midiand).	Motor's to be tested;	ereaned a renairy
pumps to be repla	icea.		
0 DIII/D 1 T=+	5-1/2" PFT & SN on 2-3/8" p	rod tha to +8310 (ton	perf). Break
Z. KIM W/D.J. ITTan	KCL fresh wtr w/1 gpt NE-13	(NF agent). Spot 2000	gals wash fluid
circulation W/Z%	elow) to SN. Round trip tool	thru nerfs sirculating	a @ ±2 BPM. (Do
(see additives be	STOWY TO SHE KOUNG CETP COOL	ciira peris circaraciii	.5 (
not go below 8400	, .,		
2 Cina 2000 and 11	5% NEFE HC1 w/additives to S	N. SI backside. PMP 15	000 gals 15% NEFE HCl
5. Circ Suuu gais 1:	thru perfs in the injection	mode. (Do not ao bel	ow 8400'.) Repeat
while moving PFI	of back to top perf (±8310).	'Pmp 1500 gals 2% KCl	fresh wtr w/1 gpt
WILLE pulling to	e acid into perfs. SI 15 mi	n. '	•
ME-19 CO GISHIGO	Judia into perio. Of 10 mi		
4. POH w/tbg & PFT.			·
Te TOIL MY COS COTTE			
			•
,			
	above is true and complete to the best of m	y knowledge and helief.	
Descon castill fuer the information	and a transfer of the peat of the	;	
$(1) \cup V$	b	A	5/20/86
·· JUIIm for	TITLE ASSOC	<u>iate Accountant</u> .	
ORIGINAL SIGNED B	Y JERRY SEXTON		MAY 2 6 1986
DISTRICT I SH			DATE

MAN SERVICE