State of New Mexico Form C-103 Submit 3 Copies Energy, Minerals and Natural Resources Department Revised 1-1-89 to Appropriate District Office OIL CONSERVATION DIVISION DISTRICTI WELL API NO. P.O. Box 1980, Hobbs, NM 88240 P.O. Box 2088 Santa Fe, New Mexico 87504-2088 DISTRICT II P.O. Drawer DD, Artesia, NM 88210 5. Indicate Type of Lease STATE FEE 📙 1000 Rio Brazos Rd., Aztec, NM 87410 6. State Cil & Gas Lease No. E-8165 SUNDRY NOTICES AND REPORTS ON WELLS ( DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A 7. Lease Name or Unit Agreement Name DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) Southern Union State Type of Well: WELL X OTHER 2. Name of Operator 8. Well No. Marks & Garner 9. Pool name or Wildcat 3. Address of Operator P O Box 70 Midway Abo 4. Well Location : 660 Feet From The North Line and 660 Feet From The West thip 17S Range 37E 10. Elevation (Show whether DF, RKB, RT, GR, etc.) 16 Section Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PLUG AND ABANDON |X REMEDIAL WORK ALTERING CASING PERFORM REMEDIAL WORK **CHANGE PLANS** COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT **TEMPORARILY ABANDON** CASING TEST AND CEMENT JOB **PULL OR ALTER CASING** OTHER:\_ OTHER:\_ 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. Set CIBP 8750' with 25' cement on top Load hole with #10 Brine with 25 sacks gel Shoot & pull 6500' Spot 50 sacks cement in and out of stub Spot 50 sacks 3500' - 3600' Cut 8 5/8" - 2000' spot 50 sack plugin & out 2000'

I hereby certify that the information above is true and complete to the best of my	knowledge and belief.	
SKONATURE JEST SKILL	me Partner	DATE 9-29-92
TYPE OR PRINT NAME James H. Buddy Garner		TELEPTIONE NO. 396-5326
(This anace for State Use)		

OCT 0 1'92

2000年4月1日 · 1000年1

CONDITIONS OF ATTROVAL, IF ANY:

Spot 50 sacks 314'

10 sack plug at surface - install dry hole marker

RECEIVED SEP 3 0 1992

OCD HOBBS OFFICE