

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>

5. State Oil & Gas Lease No.

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. Unit Agreement Name
2. Name of Operator <b>Amerada Division, Amerada Hess Corporation</b>		8. Farm or Lease Name <b>L. Cooper</b>
3. Address of Operator <b>P. O. Drawer 817 - Seminole, Texas 79360</b>		9. Well No. <b>2</b>
4. Location of Well UNIT LETTER <b>C</b> <b>660</b> FEET FROM THE <b>North</b> LINE AND <b>3300</b> FEET FROM THE <b>East</b> LINE, SECTION <b>2</b> TOWNSHIP <b>17S</b> RANGE <b>38E</b> NMPM.		10. Field and Pool, or Wildcat <b>Knowles Devonian</b>
15. Elevation (Show whether DF, RT, GR, etc.) <b>3709' DF</b>		12. County <b>Lea</b>

16.

## Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

### NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

### SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Spot <sup>40</sup> sack cement plug from 12,490' to 12,370'. Cut off 5-1/2" OD csg. at 5800'. Spot <sup>25</sup> sack cement plug from 5800' to 5742'. Spot 30 sack cement plug in 8-5/8" OD csg and 7-7/8" hole from 4760' to 4850'. Cut off 8-5/8" OD csg at 800'. Spot 40 sack cement plug from 825' to 775'. Spot 40 sack cement plug from 310' to 360' and 10 sack cement plug from 0' to 11'. Install permanent marker and clean location.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED J. R. Enloe TITLE Regional Manager DATE July 12, 1971

APPROVED BY [Signature] TITLE STAFF DATE [Signature]

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

JUL 14 1971

OIL CONSERVATION COMM.  
HOBBS, N. M.