NEW MEXICO OIL CONSERVATION COMMISSION Santa Fe, New Mexico

MISCELLANEOUS REPORTS ON WELLS

Submit this report in TRIPLICATE to the District Office, Oil Conservation Commission, within 10 days after the work specified is completed. It should be signed and filed as a report on Beginning Drilling Operations, Results of test of casing shut-off, result of plugging of well, result of well repair, and other important operations, even though the work was witnessed by an agent of the Commission. See additional instructions in the Rules and Regulations of the Commission.

	Indicate Nature of Report by Checking Be	low
REPORT ON BEGINNING DRILLING OPERATIONS	REPORT ON RESULT OF TEST OF CASING SHUT-OFF	REPORT ON REPAIRING WELL
REPORT ON RESULT OF PLUGGING WELL	REPORT ON RECOMPLETION OPERATION	REPORT ON (Other)
	March 21, 1955	Hobbs, New Mexico
Following is a report on the work d	lone and the results obtained under the heading r	noted above at the
(Company of Oper	ation atori	W. P. Cone
_	Well No. 2	(Lease)in the
	South Knowles Devonian Pool,	
	March 14-17, 1955	
Notice of intention to do the work (2008)	(was not) submitted on Form C-102 on	(Cross out incorrect words) , 19
and approval of the proposed plan ()	(supplied to the first to the f	
DETAILI	ED ACCOUNT OF WORK DONE AND RESU	
Ran 277 Jts and cut jt (16 casing. Set and comented ottom. Haximum pressure 16-14-55. After waiting ever 30 hours no drop in pressure. Dr. asing shee with 800# for 30. Witnessed by		r P-110, N-60, and S-95 1 and 100 sacks Neat on plete by Howes 10:15PM for 30 minutes. There s 12,155'. Tested below
Ran 277 Jts and cut jt (15 casing. Set and comented ottom. Haximum pressure 16-14-55. After waiting ever 30 hours no drop in pressure. Dr. saing shee with 800# for 30	2,139') 7" OD 29#, 26# and 23# G at 12,155' with 350 sacks AE Ge 400#. Plug at 12,071'. Job comes, tested 7" easing with 1000# illed ement plug from 12,071' t minutes. No drep in pressure.	r P-110, N-60, and S-95 1 and 100 sacks Neat on plete by Howee 10:15PM
Ran 277 Jts and cut jt (1.5 casing. Set and comented of tem. Haximum pressure 1.014-55. After waiting ever 30 hours no drop in pressure. Drawing shoe with 800# for 30 with 800	2,139') 7" OD 29#, 26# and 23# G at 12,155' with 350 sacks AE Ge A00#. Plug at 12,071'. Job com rs, tested 7" easing with 1000# illed ement plug from 12,071' t minutes. No drep in pressure. Culf Oil Cerpera tion (Company)	P-110, N-60, and S-95 1 and 100 sacks Neat on plete by Howee 10:15PM for 30 minutes. There s 12,155'. Tested below Drilling Foresen (Title)
Ran 277 Jts and cut jt (1.5 casing. Set and comented of them. Haximum pressure 1.6-14-55. After waiting ever 30 hours as no drop in pressure. Dr. saing shoe with 800# for 30. Witnessed by	2,139') 7" OD 29#, 26# and 23# G at 12,155' with 350 sacks At Ge 400#. Plug at 12,071'. Job com rs, tested 7" easing with 1000# illed ement plug from 12,071' t minutes. No drep in pressure. Company) I hereby certify that to the best of my king.	P-110, N-80, and S-95 1 and 100 sacks Neat on plete by Howee 10:15PM for 30 minutes. There s 12,155'. Tested below the information given above is true and complet nowledge. Supt. of Frod.