

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.
7. Unit Agreement Name
8. Farm or Lease Name D. F. Willhoit
9. Well No. 2
10. Field and Pool, or Wildcat South Knowles Devonian
12. County Lea

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator Jake L. Hamon
3. Address of Operator 611 Petroleum Building, Midland, Texas 79701
4. Location of Well UNIT LETTER <u>M</u> , <u>660</u> FEET FROM THE <u>South</u> LINE AND <u>660</u> FEET FROM THE <u>West</u> LINE, SECTION <u>18</u> TOWNSHIP <u>17S</u> RANGE <u>39 E</u> NMPM.
15. Elevation (Show whether DF, RT, GR, etc.) 3672' Gr.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐
OTHER ☐

PLUG AND ABANDON ☒
CHANGE PLANS ☐
OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOBS ☐
OTHER ☐
ALTERING CASING ☐
PLUG AND ABANDONMENT ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Pull rods and tubing. Drill out Model "D" packer at 10,225' with drilling bailer to 12,040'
2. Set cast iron bridge plug in 5½" casing at 11,950'. Dump 4 sacks (35') of cement on top of plug. Note Top of Devonian at 12,043'.
3. Run tubing and circulate hole with 9.5# mud. Pull tubing.
4. Shoot and pull 5½" casing from approximately 5390'.
5. Set cement plugs as following:
 - a. 100' (35 sks) in and out stub of 5½" casing.
 - b. 200' (70 sks) from 5100' back to 4900'. Tag plug. (Note: 9 5/8" set at 5000.5')
 - c. 100' (40 sks) at top of salt at 2500'.
 - d. 10 sacks in top of 9 5/8" casing and set a 4" OD permanent marker.
6. Work to start approximately August 23, 1978.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Cliff W. Barton TITLE Petroleum Engineer DATE August 1, 1978
APPROVED BY John Runyan TITLE Geologist DATE AUG 3 1978
CONDITIONS OF APPROVAL, Geologist