N. M.	. O. C. C. COPY	Budget Bureau No. 42-R358.4.
Form 3-831a		Approval expires 12-31-60.
(Feb. 1951) (SUBMIT IN TRIPLICATE)		Land Office
		Lease No.
ADAKA	ED STATES	[] Unit
	OF THE INTERIOR	
AUG D ISO GEOLO	GICAL SURVEY	RECEIVED
R BROWN GINEER		
ACTING DISTRICT ENGINEER		AUG 2 1 1951
SUNDRY NOTICES A	ND REPORTS OF	WELL'S
		der DE
NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER	g•-
NOTICE OF INTENTION TO CHARGE PLANS	ICE OF INTENTION TO TEST WATER SHUT-OFF SUBSEQUENT REPORT OF ALTERI	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	NOTICE OF INTENTION TO SHOOT OR ACIDIZE	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		
	NATURE OF REPORT, NOTICE, OR OTHER	
		Jaly 20, 19 ⁶¹
Yates Buffalo Fed		XX
Well No is located ft. from	line and t. fr	om $\left\{ \frac{\mathbf{E}}{\mathbf{W}} \right\}$ line of sec. 13
	(5)	(w)
C-N#/4 N#/4 13 185	326 NJX	
(1/ Sec. and Sec. No.) (Twp.)	(Range) (Meridian)	New Hexico
(Field) (County o	r Subdivision)	(State or Territory)
The elevation of the derrick floor above sea lev	el is ft.	
DETAI	LS OF WORK	
(State names of and expected depths to objective sands; show and	as, weights, and lengths of proposed ca	sings; indicate mudding jobs, cement-
ing points, and all o	ther important proposed work)	
damentation with the cost 1000	non-ant Amaza 290619 to 1	al and Frankrad app 5-3/28
Circulated hole with jel. Set 100*	ceneral flow Stor. to	
casing at 2490". Pulled same. Ran to	ubing. Flaced 100 ⁴ ce	ment plug from 1140° to
1240". Pulled tubing. Snocked off 8	-5/8" casing at 450".	Pulled same and placed
	min a a	N
10° causant plug at surface and regu	lation dry hole marks	
		RECEIVED
		111 0 7 1051
		JUL 27 1961
		DE LE LEGELDERUAL SURVEY
l understand that this plan of work must receive approval in	writing by the Geological Survey befo	re operations may be commariew. MEXICO
Company		
320 Carper Bldg.		
Address		C C
Artesis, New Mexico		us Monnar
ALL	By Semi	
	Title Ge	a. Supt.
	1 ILIC	GP0 862040
		GPD 8520 NO
		GPO 852040