

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

| | |
|------------------------|--|
| NO. OF COPIES RECEIVED | |
| DISTRIBUTION | |
| SANTA FE | |
| FILE | |
| U.S.G.S. | |
| LAND OFFICE | |
| OPERATOR | |

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

| | |
|---|------------------------------|
| 5a. Indicate Type of Lease | |
| State <input checked="" type="checkbox"/> | Fee <input type="checkbox"/> |
| 5. State Oil & Gas Lease No. | |
| B-1501 | |

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT - " (FORM C-101) FOR SUCH PROPOSALS.)

| | |
|--|--------------------------------|
| 1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/> | 7. Unit Agreement Name |
| 2. Name of Operator | Central Vacuum Unit |
| 3. Address of Operator | 8. Farm or Lease Name |
| P. O. Box 728, Hobbs, New Mexico 88240 | Central Vacuum Unit |
| 4. Location of Well | 9. Well No. |
| UNIT LETTER <u>0</u> <u>660</u> FEET FROM THE <u>South</u> LINE AND <u>1980</u> FEET FROM | 33 |
| THE <u>East</u> LINE, SECTION <u>30</u> TOWNSHIP <u>17-E</u> RANGE <u>35-E</u> N.M.P.M. | 10. Field and Pool, or Wildcat |
| | Vacuum Grayburg |
| | San Andres |
| 15. Elevation (Show whether DF, RT, GR, etc.) | 12. County |
| 3989' (DF) | Lea |

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

| | | | |
|--|---|--|---|
| NOTICE OF INTENTION TO: | | SUBSEQUENT REPORT OF: | |
| PERFORM REMEDIAL WORK <input type="checkbox"/> | PLUG AND ABANDON <input type="checkbox"/> | REMEDIAL WORK <input type="checkbox"/> | ALTERING CASING <input type="checkbox"/> |
| TEMPORARILY ABANDON <input type="checkbox"/> | CHANGE PLANS <input type="checkbox"/> | COMMENCE DRILLING OPNS. <input type="checkbox"/> | PLUG AND ABANDONMENT <input type="checkbox"/> |
| PULL OR ALTER CASING <input type="checkbox"/> | OTHER <input type="checkbox"/> | CASING TEST AND CEMENT JOBS <input type="checkbox"/> | |
| | | OTHER <u>Deepen in Same Zone & Treat</u> | <input checked="" type="checkbox"/> |

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Rigged up. Pull rods & pump. Install BOP. Pull tubing.
2. Clean out & deepen to 4705' (TD).
3. Spot 500 gals. 50-50 Xylene & 15% NEFE Acid in open-hole section.
Spot 15 Bbls. Ammonium bicarbonate across open-hole. Squeeze addl. 15 Bbls. in to formation.
4. Acidize W/7000 gals 15% NEFE Acid in 4-stages using 1100# rock salt & 1100# moth balls between stages. Flush W/75 Bbls. Brine water.
5. Install pumping equip. . . Test & place on production.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE Asst. Dist. Mgr. DATE 6-23-83

APPROVED BY [Signature] TITLE DATE

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

JUN 24 1983

O.C.D.
HCSBS OFFICE