NUMBER OF COPIES ECEIVED										
JANTA FT       JANTA FT         SANTA FT       Image: Straiburtion         FILE       Image: Straiburtion         VISGIS       Image: Straiburtion         LAND OFFICE       Image: Straiburtion         TENNERORYER       OIL         MISCELLANEOUS REPORTS ON WELLS										
PRORATION OFFICE										
(Submit to appropriate District Office as per Commission Rule 1106)										
Name of Company Shell Oil Company P, O. Box 1858, Roswell, New Mexico 88201										
Lease	011011		Vell No. Un			Township		Mex10 Range	co 88201	
	State W		2	0	26	<u> </u>	17-S		35-E	
Date Work Performed Pool Dec. 11 thru 20, 1964 Vacuum-Abo						County	Lea			
THIS IS A REPORT OF: (Check appropriate block)										
Beginning Drilling Operations Casing Test and Cement Job Other (Explain):										
🔲 Pluggin	Plugging X Remedial Work									
Detailed account of work done, nature and quantity of materials used, and results obtained.										
<ol> <li>Killed well with water and unseated packer.</li> <li>Ran tubing and reset packer at 8879' and pressured to 1350 psi for 30 minutes - no</li> </ol>										
pressure drop. Released and pulled packer and tubing.										
3. Reran tubing and set bridge plug at 8875' and packer at 8839'. Swabbed well. No										
indication of communication. 4. Released packer and picked up bridge plug. Reset bridge plug at 8839; and packer at 8776; with 18,000 psi, straddling perfs 8782;-8788; and 8797;-8834;. Swabbed well and										
well stabilized.										
5. Killed well, released packer, lowered tubing and retrieved bridge plug. Pulled tubing, packer and bridge plug. Set Baker cast from bridge plug at 88001 plugging off contra										
packer and bridge plug. Set Baker cast iron bridge plug at 8840' plugging off casing perfs. 8845'-8851'. Dumped 1 sack cement on top of bridge plug.										
6. Hung 282 joints (8657') of 2" EUE, 8rd, tubing at 8673' with 4' sub 8668-8673' open										
hole on bottom; Guiberson KVL Packer 8659'-8669' with rubber at 8663'; HHD 8658-8659'; 2" SN at 8657'; 4' x 2" sub at 8653'-8657'; 2' x 2" sub on landing donut at top of										
2" SN at 0057'; 4' x 2" sub at 0053'-0057'; 2' x 2" sub on landing donut at top of string. Set packer with 18,000 psi.										
7. Swabbed well & recovered load. (Over)										
Witnessed by M. R. Dillon Production					Foreman Shell Oil Company					
M. R. Dillon Production Foreman Shell Oil Company FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY										
				L WELL C	ATA	T				
D F Elev.				8056	Producing Interval Completion Date 8956' 8695'-8851' June 19, 1962					
Tubing Diam	<u>3925</u>	Tubing Depth	<u> </u>		ng Diame		Oil String		me 19, 1962	
	_	4 1/2" 8990'								
Perforated Interval(s) 8695-87381, 8740-87561, 8782-87881, 8797-88341, 8845-8847-88511										
Open Hole Interval         Producing Formation(s)										
- Abo RESULTS OF WORKOVER										
Test	Date of Test	Oil Production B P D	Gas Prod MCF			roduction PD	GOR Cubic feet/B		Gas Well Potential MCFPD	
Before Workover	11-21-64	112			1	38	636			
After Vorkover	12-20-64	(based on 56 348	8 <b>BO in</b> 4 1	hours)	'n	ione			1	
I hereb						eby certify that the information given above is true and complete e best of my knowledge.				
Approved by					Name Original Signed By: V. L. King V. L. King					
Title					Position					
					Acting Senior Exploitation Engineer					
						Shell Oil Company				

8. In 24 hours flowed 348 BO, no water (rated on 58 BO in 4 hours) on 24/64" choke.

٠

T

· · · · · ·