| DISTRIBUTION ANTA FE NEW MEXICO OIL CONSERVATION COMMISSION LE S.G.S. AND OFFICE PERATOR | Supersedes Old C-102 and C-103 |
|---|--------------------------------|
| LE .s.g.s. AND OFFICE | |
| .s.g.s. AND OFFICE | Effective 1-1-65 |
| AND OFFICE | |
| | 5a. Indicate Type of Lease |
| PERATOR | State 🗶 Fee. |
| | 5. State Oil & Gas Lease No. |
| | B-155-1 |
| SUNDRY NOTICES AND REPORTS ON WELLS | |
| SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.) | |
| | 7. Unit Agreement Name |
| OIL GAS WELL OTHER- | |
| Name of Operator | 8, Farm or Lease Name |
| Tevesa Tas | New Years and the years |
| Texaco Inc. Address of Operator | New Mexico 'O' St. MCT |
| | |
| P. O. Box 728 Hobbs, New Mexico 88240 | 10. Field and Pool, or Wildcat |
| Location of Well | |
| UNIT LETTER B , 467 FEET FROM THE West LINE AND 1980 FEET | FROM VACUUM Blinebry |
| | |
| THE North LINE, SECTION 36 TOWNSHIP 17S RANGE 34B | NMPM. (()) |
| THE TOWNSHIP SECTION | |
| 15. Elevation (Show whether DF, RT, GR, etc.) | 12. County |
| | |
| 4016' (DF) | Les |
| Check Appropriate Box To Indicate Nature of Notice, Report o | r Other Data |
| NOTICE OF INTENTION TO: SUBSEQU | JENT REPORT OF: |
| | |
| ERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK | ALTERING CASING |
| EMPORARILY ABANDON COMMENCE DRILLING OPNS. | PLUG AND ABANDONMENT |
| | TEGG AND ABANDONMENT |
| ULL OR ALTER CASING LOST CASING TEST AND CEMENT JOB | 30-0-0 |
| OTHER | Status Change X |
| OTHER | |
| work) SEE RULE 1903. | |
| Ran CIBP in Blinebry string and set @ 6375'. Blinebry abandoned Junwell is a single completion in the Vacuum Glorieta. | ne 28, 1974. Subject |
| Ran CIBP in Blinebry string and set @ 6375'. Blinebry abandoned Ju | ne 28, 1974. Subject |

CONDITIONS OF APPROVAL, IF ANY:

01