

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

WELL API NO.

30-025-20143

5. Indicate Type of Lease

STATE ☒ FEE ☐

6. State Oil / Gas Lease No.

B-270

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT
(FORM C-101) FOR SUCH PROPOSALS.

1. Type of Well: OIL ☒ GAS ☐
WELL ☒ WELL ☐ OTHER ☐

2. Name of Operator
TEXACO EXPLORATION & PRODUCTION INC.

3. Address of Operator
205 E. Bender, HOBBS, NM 88240

4. Well Location
Unit Letter K 1650 Feet From The WEST Line and 1650 Feet From The SOUTH Line
Section 25 Township 17S Range 34E NMPM LEA COUNTY

10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4003' GL

7. Lease Name or Unit Agreement Name

VACUUM GLORIETA WEST UNIT

8. Well No.

34

9. Pool Name or Wildcat

VACUUM GLORIETA

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

REMEDIAL WORK ☒

ALTERING CASING ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

COMMENCE DRILLING OPERATION ☐

PLUG AND ABANDONMENT ☐

PULL OR ALTER CASING ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

OTHER: SQZ LOWER/PERF UPPER GLORIETA ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

4-05-00: MIRU. UNLOAD, RACK, TALLY WS. NDWH. NUBOP. TIH W/BIT, DC'S, TBG. TAG @ 5873'. TEST CSG TO 500 PSI-OK. DISPL W/10# BRINE. DRLD CMT TO CIBP @ 5900'.
4-06-00: DRILL CIBP @ 5900'. PSH TO 6324'. CIRC CLN. TIH W/PKR, SN, & TBG TO 5896'. SET PKR. TEST CSG-OK. REL PKR & TOH. TIH W/CMT RET, TBG TO 5893'.
4-07-00: PUMP THRU RET W/35 BBLS. SET RET @ 5893'. TEST TBG TO 2000 PSI-OK. PSI CSG TO 500-OK. MIX 50 SX CL C W/4% D-156, .3% D-65, .2% D-46, 2# SK COALITE, & 100 SX CL C NEAT. FLSH W/19 BBLS.
4-10-00: TIH W/ BIT, DC'S & TBG. TAG @ 5893'. BREAK CIRC. DRILL CMT TO 5995'. TEST CSG TO 500 PSI-OK. DISPL W/2% KCL.
4-11-00: TIH W/PERF GUN & PERF CSG IN GLORIETA FORM 5846-5946, 5966-82. TIH W/PKR, SN ON TBG. SET PKR @ 5802'. LOAD & TEST BACKSIDE TO 500#-OK. RU SWAB LINE TO FRAC TANK.
4-12-00: PSI CSG TO 500-OK. ACIDIZE GLORIETA PERFS 5846-5982 W/7000 GALS 15% NEFE HCL, & 1500# RK SLT. RU & SWAB FL @ 300'. END FL @ 3400'.
4-13-00: FL @ 3400'. END FL @ 4800'. REL PKR. TIH TO 5995'. NO SALT FILL. RESET PKR @ 5802'. END FL @ 4600'.
4-14-00: PUMP 30 GALS ALPHA 160 W/5 GALS TECHNI WET 4273, MIXED W/20 BFW. FLSH W/44 BBLS, PUMP @ 1 1/2 BPM @ 700 PSI. REL PKR. TIH W/GAS ANCHOR, SN, BLAST JT, TBG, TAC. NUBOP. SET TAC. NUWH. BTM OF STRING @ 9'. KB @ 5995'. SN @ 5985'. TAC @ 5757'.
4-17-00: TIH W/PMP, ON/OFF TOOL, LIFT SUB, K-BARS, RDS. RIG DOWN.
4-27-00: ON 24 HR OPT. PUMPED 73 BO, 63 BW, & 14 MCF. PERFS 5846-5982' VACUUM GLORIETA.
FINAL REPORT

I hereby certify that the information above is true and complete to the best of my knowledge and belief

SIGNATURE

J. Denise Leake
J. Denise Leake

TITLE

Engineering Assistant

DATE 5/8/00

TYPE OR PRINT NAME

Telephone No. 397-0405

(This space for State Use)

APPROVED

CONDITIONS OF APPROVAL IF ANY

TITLE

DATE