

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERAT 4	

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-77

5a. Indicate Type of Lease	
State ☒	Fee ☐
5. State Oil & Gas Lease No.	
B-1056	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL ☒ GAS WELL ☐ OTHER ☐		7. Unit Agreement Name
Name of Operator		8. Farm or Lease Name
TEXACO Inc.		New Mexico "Q" State
Address of Operator		9. Well No.
P. O. Box 728, Hobbs, New Mexico 88240		5
Location of well		10. Field and Pool, or Wildcat
UNIT LETTER <u>O</u> <u>460</u> FEET FROM THE <u>South</u> LINE AND <u>2080</u> FEET FROM		Vacuum Glorieta
THE <u>East</u> LINE, SECTION <u>25</u> TOWNSHIP <u>17-S</u> RANGE <u>34-E</u> NMPM.		
15. Elevation (Show whether DF, RT, GR, etc.)		12. County
3997' (GR)		Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
-------------------------	-----------------------

FORM REMEDIAL WORK ☐ TEMPORARILY ABANDON ☐ PL OR ALTER CASING ☐ OTHER <u>Addl Perfs in Glorieta</u> ☒	PLUG AND ABANDON ☐ CHANGE PLANS ☐ REMEDIAL WORK ☐ COMMENCE DRILLING OPNS. ☐ CASING TEST AND CEMENT JOBS ☐ OTHER ☐	ALTERING CASING ☐ PLUG AND ABANDONMENT ☐
---	--	---

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. RIG UP. PULL RODS AND PUMP. INSTALL BOP. PULL TUBING.
2. CLEAN OUT 2 7/8" GLORIETA ACASING STRING TO 6310' (NEW PBTD).
3. PERFORATE 2 7/8" TUBING W/2-JSPF @ 5941, 65, 68, 72, 73, 98, 6004' 06, 08, 6213, 14, 15, 16, 33, 34, 35, 36, 62, 63, 64, 65, 66, 87, 88, 89, & 6290'.
4. SET RBP BELOW PERFS AND PKR @ 6150'.
5. ACIDIZE PERFS 6213-6290' W/3000 GALS 15% NEFE ACID, 250# ROCK SALT AND 55 GALS SCALE INHIBITOR.
6. SET RBP @ 6150' AND PKR @ 5890'. ACIDIZE PERFS 5941-6094' W/3000 GALS 15% NEFE ACID, 250# ROCK SALT AND 5 GAL SCALE INHIBITOR.
7. INSTALL PRODUCTION EQUIPMENT. TEST AND PLACE ON PRODUCTION.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

<u>W.B. Guder</u>	TITLE <u>District Operations Mgr</u>	DATE <u>10-24-84</u>
<u>Eddie W. Seay</u>	TITLE <u>Oil & Gas Inspector</u>	DATE <u>OCT 29 1984</u>
CONDITIONS OF APPROVAL, IF ANY:		