

OIL CONSERVATION DIVISION

DISTRICT I P.O. Box 1980, Hobbs, NM 88240
DISTRICT II P.O. Box Drawer DD, Artesia, NM 88210
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410

P.O. Box 2088 Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-20179
5. Indicate Type of Lease STATE [X] FEE []
6. State Oil / Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT (FORM C-101) FOR SUCH PROPOSALS.
1. Type of Well: OIL WELL [X] GAS WELL [] OTHER []
2. Name of Operator TEXACO EXPLORATION & PRODUCTION INC.
3. Address of Operator P.O. Box 2100, Denver Colorado 80201
4. Well Location Unit Letter K 2310 Feet From The WEST Line and 2310 Feet From The SOUTH Line
Section 36 Township 17-S Range 34-E NMPM LEA COUNTY
10. Elevation (Show whether DF, RKB, RT,GR, etc.)

7. Lease Name or Unit Agreement Name VACUUM GLORIETA WEST UNIT
8. Well No. 86
9. Pool Name or Wildcat VACUUM GLORIETA

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data
NOTICE OF INTENTION TO:
PERFORM REMEDIAL WORK [] PLUG AND ABANDON []
TEMPORARILY ABANDON [] CHANGE PLANS []
PULL OR ALTER CASING []
OTHER: []
SUBSEQUENT REPORT OF:
REMEDIAL WORK [] ALTERING CASING []
COMMENCE DRILLING OPERATION [] PLUG AND ABANDONMENT []
CASING TEST AND CEMENT JOB []
OTHER: RE-COMPLETION [X]

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.
1. MIRU DAWSON PULLING UNIT #222. PULL AND LAY DOWN RODS & PUMP. 07-11-97.
2. RU HALLIBURTON LOGGING SERV. TAG CMT @ 6199'(PBSD). RAN GAMMA RAY-COLLAR LOG FROM 6199'-5000'. SET 5-1/2" CIBP @ 5833'. STRAP IN 2-7/8" TBG. TAG CIBP @5830'. SET 15 PTS WEIGHT ON CIBP-HELD. 07-12-97.
3. RU KEY RIG. SPOT EQUIPMENT. UNLOAD DRILLPIPE AND STRAP PIPE. 07-15-97.
4. TAG @5828.PU MILL AND WHIPSTOCK. TIH. RU WL. TIH W/GRYO.ORIENT WHIPSTOCK SET. WHIPSTOCK W/194 DEGREE DIRECTION. CUT WINDOW IN CASING W/ STARTER MILL. TIH W/PIPE & WATERMELLON MILL. RU SWIVAL TOP OF WHIPSTOCK @ 5809. 07-16-97.
5. MILL WINDOW AND 4' FORMATION. TOP OF WINDOW @ 5808', BOTTOM OF WINDOW @ 5821'. ORIENT GYRO TO 201. 07-17-97.
6. PULL GYRO AND CHANGE OUT. DRILL HORIZONTAL HOLE TO MD 6918'. 07-18-97.
7. CHANGE BHA. 07-19-97.
8. RIH W/ RBP TO 4862'. STUCK, ATTEMPTED TO SET. DID NOT SET. PULL OFF RBP. POOH W/ WL. MAKE UP & PICKED UP FISHING TOOL. LATCHED ON & SHEAR SETTING TOOL OFF RBP. 07-20-97.
9. TOH W/F/T & SETTING TOOL. TEST RBP TO 1100 PSI. REL RIG @ 1300 HOURS. 07-21-97.
10. SI. PREP TO COMPLETE. 07-22-97.
11. PRODUCTION PUT ON PUMP TEST. 07-29-97.
12. POT WITH SUBMERSIBLE PUMP FOR 24 HOURS - MADE 92 BO, 256 BW, 24 MCF OF GAS. 08-08-97.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.
SIGNATURE C.P. Basham /SRH TITLE Eng. Assistant. DATE 8/20/97
TYPE OR PRINT NAME Sheilla D. Reed-High Telephone No. (303)793-4851
ORIGINAL SIGNED BY CHRIS WILLIAMS, DISTRICT I SUPERVISOR
APPROVED
CONDITIONS OF APPROVAL, IF ANY: TITLE DATE