

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION  
P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-79

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL ☒ GAS WELL ☐ OTHER ☐

Name of Operator  
Big "6" Drilling Company

Address of Operator  
c/o Oil Reports & Gas Services, Inc., Box 763, Hobbs, NM 88241

Location of Well  
UNIT LETTER E 1980 FEET FROM THE North LINE AND 660 FEET FROM  
THE West LINE, SECTION 5 TOWNSHIP 19S RANGE 35E NMPM.

5a. Indicate Type of Lease  
State ☐ Fee ☒

5. State Oil & Gas Lease No.

7. Unit Agreement Name

8. Farm or Lease Name  
Ora Jackson

9. Well No.  
1

10. Field and Pool, or Wildcat  
Scharb Bone Springs

12. County  
Lea

15. Elevation (Show whether DF, RT, GR, etc.)  
3920 GL

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

It is proposed to plug & abandon as follows:

1. Fish tubing & packer & clean up 4 1/2" casing
2. Cut & pull 4 1/2" casing from approximately 4200
3. Spot 100' cement plug across 4 1/2" stub
4. Spot 100' cement plug across 8 5/8" casing shoe at 4004
5. Spot 100' cement plug at 3500
6. Perf 8 5/8" casing at 1500 with 4 holes & circulate cement to surface
7. Set 10' plug at surface with regulation marker
8. Clean & level location

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Jerry Sexton TITLE Agent DATE 11/28/84

ORIGINAL SIGNED BY JERRY SEXTON  
DISTRICT 1 SUPERVISOR

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY:

NOV 29 1984