	,			COMMISSION
			. AC	INS. COMMISSION
			N.M. JILO P.O. BOX	1980 Budget Bureau No. 1004-0135 Expires: March 31, 1993
Form 3160-5	UNITED S	TATES	P.O. BC	Budget Burgey No. 1004 0125
(June 1990)	DEPARTMENT OF	THE INTERIOR	40885	Budget Bureau No. 1004-0135 Expires: March 31, 1993
	BUREAU OF LAND	MANAGEMENT		5. Lease Designation and Serial No.
				NM-04371B
	INDRY NOTICES AND	554.	5	6. If Indian, Allottee or Tribe Name
	for proposals to drill or t			
Use	APPLICATION FOR PER	MII — " for such propos	als	
	SUBMIT IN T	RIPLICATE		7. If Unit or CA, Agreement Designation
1. Type of Well	*************		25 1925	8910115660
X Well Gas Well	Other	l,	~ K025	8. Well Name and No.
2. Name of Operator	·	10 0/87		Young Unit #27
YATES PETROLEUM	1 CORPORATION	(505) 748-	-1471) /	9. API Well No.
3. Address and Telephone No.				30-025-20210
105 South 4th St., Artesia, NM 88210			10. Field and Pool, or Exploratory Area	
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)				Young Queen
330' FSL & 330' FWL of Section 21-T18S-R32E (Unit M, SWSW)				11. County or Parish, State
550 10H d 550	THE OF DECLION 21	-1109-K32E (OHIC F	, SWSWJ	
				Lea Co., NM
12. CHECK APP				
		INDIGATE NATURE (	OF NUTICE, REPO	ORT, OR OTHER DATA
TYPE OF SUB	TYPE OF SUBMISSION TYPE OF ACTION			
<u> </u>				· · · · · · · · · · · · · · · · · · ·
L_] Notice of Inter	at	X Abandonment		Change of Plans
		Recompletion		L New Construction
X Subsequent Re	port	Plugging Back		Non-Routine Fracturing
		Casing Repair		Water Shut-Off
L.J Final Abandon	iment Notice	Altering Casing		Conversion to Injection
		[] Other		Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form )
13. Describe Proposed or Complete	d Operations (Clearly state all pertiner	nt details, and give pertinent dates, in	cluding estimated date of star	ting any proposed work. If well is directionally drilled,
-	and measured and true vertical depths	-	-	
9-9-11-95 - Move	ed in and rigged up	pulling unit. N	ippled up BOP.	Rigged up wireline. TIH
				4000'. Rigged down wire-
				ps. Estimate free point
at 1383'. Nipp.	led up BOP. TIH w:	ith 2-3/8" tubing	and tagged CIB	P at 4000'. Spotted 48
bbls plug mud f	rom 4000-1000' (in	4-1/2" casing).	Mixed and pump	ed 15 sacks Class C cement
		$\mathbf{D} \cap \mathbf{U}$ $\mathbf{U} \to \mathbf{U} + $		
from 4000-3800'	(in 4-1/2" casing)	. FOOR WILL LUDI	ng to 3450'.	Mixed and pumped 15 sacks
Class C cement :	from 3450-3250' (in	n 4-1/2" casing).	POOH with tub	Mixed and pumped 15 sacks ing to 2460'. Mixed and
Class C cement : pumped 15 sacks	from 3450-3250' (in Class C cement fro	n 4-1/2" casing). om 2460-2260' (in	POOH with tub 4-1/2" casing)	Mixed and pumped 15 sacks ing to 2460'. Mixed and . POOH with tubing. Shut
Class C cement : pumped 15 sacks down for night.	from 3450-3250' (in Class C cement fro NOTE: Notified A	n 4-1/2" casing). om 2460-2260' (in	POOH with tub 4-1/2" casing)	Mixed and pumped 15 sacks ing to 2460'. Mixed and
Class C cement : pumped 15 sacks down for night. and cement plugs	from 3450-3250' (in Class C cement fro NOTE: Notified A s.	n 4-1/2" casing). om 2460-2260' (in Andy Cortez w/BLM-	POOH with tub 4-1/2" casing) Hobbs of comme	Mixed and pumped 15 sacks ing to 2460'. Mixed and . POOH with tubing. Shut ncing plugging operations
Class C cement : pumped 15 sacks down for night. and cement plugs 9-12-95 - Nipple	from 3450-3250' (in Class C cement fro NOTE: Notified A s. ed down BOP. Pulle	n 4-1/2" casing). om 2460-2260' (in Andy Cortez w/BLM- ed up on 4-1/2" ca	POOH with tub 4-1/2" casing) Hobbs of comme sing. Rigged	Mixed and pumped 15 sacks ing to 2460'. Mixed and . POOH with tubing. Shut ncing plugging operations up wireline. TIH with
Class C cement : pumped 15 sacks down for night. and cement plugs 9-12-95 - Nipple 3-5/8" cutter an	from 3450-3250' (in Class C cement fro NOTE: Notified A s. ed down BOP. Pullo nd cut 4-1/2" casin	n 4-1/2" casing). om 2460-2260' (in Andy Cortez w/BLM- ed up on 4-1/2" ca ng at 1113'. Rigg	POOH with tub 4-1/2" casing) Hobbs of comme sing. Rigged ed down wireli	Mixed and pumped 15 sacks ing to 2460'. Mixed and . POOH with tubing. Shut ncing plugging operations up wireline. TIH with ne. Rigged up casing
Class C cement : pumped 15 sacks down for night. and cement plugs 9-12-95 - Nipple 3-5/8" cutter an equipment. POOP	from 3450-3250' (in Class C cement fro NOTE: Notified A s. ed down BOP. Pulle nd cut 4-1/2" casin H with 4-1/2" casin	n 4-1/2" casing). om 2460-2260' (in Andy Cortez w/BLM- ed up on 4-1/2" ca ng at 1113'. Rigg ng. Rigged down c	POOH with tub 4-1/2" casing) Hobbs of comme sing. Rigged ed down wireli asing equipmen	Mixed and pumped 15 sacks ing to 2460'. Mixed and . POOH with tubing. Shut ncing plugging operations up wireline. TIH with ne. Rigged up casing t. Nippled up BOP. SIFN.
Class C cement : pumped 15 sacks down for night. and cement plugs 9-12-95 - Nipple 3-5/8" cutter an equipment. POOP 9-13-95 - TIH w:	from 3450-3250' (in Class C cement fro NOTE: Notified A s. ed down BOP. Pulle nd cut 4-1/2" casin H with 4-1/2" casin ith tubing to 1163	n 4-1/2" casing). om 2460-2260' (in Andy Cortez w/BLM- ed up on 4-1/2" ca ng at 1113'. Rigg ng. Rigged down c '. Mixed and pump	POOH with tub 4-1/2" casing) Hobbs of comme sing. Rigged ed down wireli asing equipmen ed 50 sacks C1	Mixed and pumped 15 sacks ing to 2460'. Mixed and . POOH with tubing. Shut noing plugging operations up wireline. TIH with ne. Rigged up casing t. Nippled up BOP. SIFN. ass C 2% CaCl2 from
Class C cement : pumped 15 sacks down for night. and cement plugs 9-12-95 - Nipple 3-5/8" cutter an equipment. POON 9-13-95 - TIH wi 1163-1063'. POO	from 3450-3250' (in Class C cement fro NOTE: Notified A s. ed down BOP. Pulle nd cut 4-1/2" casin H with 4-1/2" casin ith tubing to 1163 OH with tubing. W0	n 4-1/2" casing). om 2460-2260' (in Andy Cortez w/BLM- ed up on 4-1/2" ca ng at 1113'. Rigg ng. Rigged down c '. Mixed and pump DC 4 hours. TIH w	POOH with tub 4-1/2" casing) Hobbs of comme sing. Rigged ed down wireli asing equipmen ed 50 sacks C1 ith tubing and	Mixed and pumped 15 sacks ing to 2460'. Mixed and . POOH with tubing. Shut ncing plugging operations up wireline. TIH with ne. Rigged up casing t. Nippled up BOP. SIFN. ass C 2% CaCl2 from tagged top of cement at
Class C cement : pumped 15 sacks down for night. and cement plugs 9-12-95 - Nipple 3-5/8" cutter an equipment. POO 9-13-95 - TIH wi 1163-1063'. POO 990'. Spotted 6	from 3450-3250' (in Class C cement fro NOTE: Notified A s. ed down BOP. Pullo nd cut 4-1/2" casin H with 4-1/2" casin ith tubing to 1163' OH with tubing. WC 60 bbls plug mud fro	n 4-1/2" casing). om 2460-2260' (in Andy Cortez w/BLM- ed up on 4-1/2" ca ng at 1113'. Rigg ng. Rigged down c '. Mixed and pump DC 4 hours. TIH w rom 990' to surfac	POOH with tub 4-1/2" casing) Hobbs of comme sing. Rigged ed down wireli asing equipmen ed 50 sacks C1 ith tubing and e. POOH w/tub	Mixed and pumped 15 sacks ing to 2460'. Mixed and . POOH with tubing. Shut ncing plugging operations up wireline. TIH with ne. Rigged up casing t. Nippled up BOP. SIFN. ass C 2% CaCl2 from tagged top of cement at ing. Rigged up wireline.
Class C cement : pumped 15 sacks down for night. and cement plugs 9-12-95 - Nipple 3-5/8" cutter an equipment. POOR 9-13-95 - TIH w: 1163-1063'. POO 990'. Spotted 6 TIH w/perforatin	from 3450-3250' (in Class C cement fro NOTE: Notified A s. ed down BOP. Pulle nd cut 4-1/2" casin H with 4-1/2" casin ith tubing to 1163' OH with tubing. WC 60 bbls plug mud fro ng guns and perfore	n 4-1/2" casing). om 2460-2260' (in Andy Cortez w/BLM- ed up on 4-1/2" ca ng at 1113'. Rigg ng. Rigged down c '. Mixed and pump DC 4 hours. TIH w rom 990' to surfac ated 4 holes at 60	POOH with tub 4-1/2" casing) Hobbs of comme sing. Rigged ed down wireli asing equipmen ed 50 sacks C1 ith tubing and e. POOH w/tub	Mixed and pumped 15 sacks ing to 2460'. Mixed and . POOH with tubing. Shut noing plugging operations up wireline. TIH with ne. Rigged up casing t. Nippled up BOP. SIFN. ass C 2% CaCl2 from tagged top of cement at ing. Rigged up wireline. pump into perfs Pressured
Class C cement : pumped 15 sacks down for night. and cement plugs 9-12-95 - Nipple 3-5/8" cutter an equipment. POOR 9-13-95 - TIH w: 1163-1063'. POO 990'. Spotted 6 TIH w/perforatin	from 3450-3250' (in Class C cement fro NOTE: Notified A s. ed down BOP. Pulle nd cut 4-1/2" casin H with 4-1/2" casin ith tubing to 1163' OH with tubing. WC 60 bbls plug mud fro ng guns and perfore	n 4-1/2" casing). om 2460-2260' (in Andy Cortez w/BLM- ed up on 4-1/2" ca ng at 1113'. Rigg ng. Rigged down c '. Mixed and pump DC 4 hours. TIH w rom 990' to surfac ated 4 holes at 60	POOH with tub 4-1/2" casing) Hobbs of comme sing. Rigged ed down wireli asing equipmen ed 50 sacks C1 ith tubing and e. POOH w/tub	Mixed and pumped 15 sacks ing to 2460'. Mixed and . POOH with tubing. Shut noing plugging operations up wireline. TIH with ne. Rigged up casing t. Nippled up BOP. SIFN. ass C 2% CaCl2 from tagged top of cement at ing. Rigged up wireline. pump into perfs Pressured
Class C cement : pumped 15 sacks down for night. and cement plugs 9-12-95 - Nipple 3-5/8" cutter an equipment. POOR 9-13-95 - TIH w: 1163-1063'. POO 990'. Spotted 6 TIH w/perforatin	from 3450-3250' (in Class C cement fro NOTE: Notified A s. ed down BOP. Pulle nd cut 4-1/2" casin H with 4-1/2" casin ith tubing to 1163 OH with tubing. WC 60 bbls plug mud fro ng guns and perfore	n 4-1/2" casing). om 2460-2260' (in Andy Cortez w/BLM- ed up on 4-1/2" ca ng at 1113'. Rigg ng. Rigged down c '. Mixed and pump DC 4 hours. TIH w rom 990' to surfac ated 4 holes at 60	POOH with tub 4-1/2" casing) Hobbs of comme sing. Rigged ed down wireli asing equipmen ed 50 sacks C1 ith tubing and e. POOH w/tub	Mixed and pumped 15 sacks ing to 2460'. Mixed and . POOH with tubing. Shut noing plugging operations up wireline. TIH with ne. Rigged up casing t. Nippled up BOP. SIFN. ass C 2% CaCl2 from tagged top of cement at ing. Rigged up wireline. pump into perfs Pressured
Class C cement : pumped 15 sacks down for night. and cement plugs 9-12-95 - Nipple 3-5/8" cutter an equipment. POOI 9-13-95 - TIH w: 1163-1063'. POO 990'. Spotted 6 TIH w/perforatin up to 850#) - no sacks Class C for	from 3450-3250' (in Class C cement fro NOTE: Notified A s. ed down BOP. Pulle nd cut 4-1/2" casin H with 4-1/2" casin ith tubing to 1163 OH with tubing. WC 60 bbls plug mud fro ng guns and perfore	n 4-1/2" casing). om 2460-2260' (in Andy Cortez w/BLM- ed up on 4-1/2" ca ng at 1113'. Rigg ng. Rigged down c '. Mixed and pump DC 4 hours. TIH w rom 990' to surfac ated 4 holes at 60 s. TIH with 2-3/8 <u>Cleaned Locatio</u> . <u>PLUGGED &amp; ABAND</u>	POOH with tub 4-1/2" casing) Hobbs of comme sing. Rigged ed down wireli asing equipmen ed 50 sacks C1 ith tubing and e. POOH w/tub '. Attempt to " tubing to 90 n. Installed ONED - FINAL R	Mixed and pumped 15 sacks ing to 2460'. Mixed and . POOH with tubing. Shut noing plugging operations up wireline. TIH with ne. Rigged up casing t. Nippled up BOP. SIFN. ass C 2% CaCl2 from tagged top of cement at ing. Rigged up wireline. pump into perfs. Pressured '. Mixed and pumped 30 regulation abandonment EPORT. P & A complete 9-12-
Class C cement : pumped 15 sacks down for night. and cement plugs 9-12-95 - Nipple 3-5/8" cutter an equipment. POO 9-13-95 - TIH w: 1163-1063'. POO 990'. Spotted 6 TIH w/perforatin up to 850#) - no <u>sacks Class C fi</u> 14. I hereby certify that the forego Signed - Walky	from 3450-3250' (in Class C cement fro NOTE: Notified A s. ed down BOP. Pulle nd cut 4-1/2" casin H with 4-1/2" casin ith tubing to 1163' OH with tubing. WC 60 bbls plug mud fr ng guns and perfora loss in 10 minutes rom 90' to surface rom 90' to surface	n 4-1/2" casing). om 2460-2260' (in Andy Cortez w/BLM- ed up on 4-1/2" ca ng at 1113'. Rigg ng. Rigged down c '. Mixed and pump DC 4 hours. TIH w rom 990' to surfac ated 4 holes at 60	POOH with tub 4-1/2" casing) Hobbs of comme sing. Rigged ed down wireli asing equipmen ed 50 sacks C1 ith tubing and e. POOH w/tub '. Attempt to " tubing to 90 n. Installed ONED - FINAL R	Mixed and pumped 15 sacks ing to 2460'. Mixed and . POOH with tubing. Shut noing plugging operations up wireline. TIH with ne. Rigged up casing t. Nippled up BOP. SIFN. ass C 2% CaCl2 from tagged top of cement at ing. Rigged up wireline. pump into perfs Pressured
Class C cement : pumped 15 sacks down for night. and cement plugs 9-12-95 - Nipple 3-5/8" cutter an equipment. POOI 9-13-95 - TIH w: 1163-1063'. POO 990'. Spotted 6 TIH w/perforatin up to 850#) - no sacks Class C fr 14. I hereby certify that the forego Signed TAL	from 3450-3250' (in Class C cement fro NOTE: Notified A s. ed down BOP. Pulle nd cut 4-1/2" casin H with 4-1/2" casin ith tubing to 1163 OH with tubing. WC 60 bbls plug mud fro ng guns and perfora loss in 10 minutes rom 90' to surface oing is rue field correct marker.	n 4-1/2" casing). om 2460-2260' (in Andy Cortez w/BLM- ed up on 4-1/2" ca ng at 1113'. Rigg ng. Rigged down c '. Mixed and pump DC 4 hours. TIH w rom 990' to surfac ated 4 holes at 60 s. TIH with 2-3/8 <u>Cleaned locatio</u> <u>PLUGGED &amp; ABAND</u> <u>Title Production</u>	POOH with tub 4-1/2" casing) Hobbs of comme sing. Rigged ed down wireli asing equipmen ed 50 sacks C1 ith tubing and e. POOH w/tub '. Attempt to " tubing to 90 n. Installed ONED - FINAL R Clerk	Mixed and pumped 15 sacks ing to 2460'. Mixed and . POOH with tubing. Shut ncing plugging operations up wireline. TIH with ne. Rigged up casing t. Nippled up BOP. SIFN. ass C 2% CaCl2 from tagged top of cement at ing. Rigged up wireline. pump into perfs. Pressured '. Mixed and pumped 30 regulation abandonment EPORT. P & A complete 9-12-
Class C cement : pumped 15 sacks down for night. and cement plugs 9-12-95 - Nipple 3-5/8" cutter an equipment. POOI 9-13-95 - TIH w: 1163-1063'. POO 990'. Spotted 6 TIH w/perforatin up to 850#) - no sacks Class C for 14. I hereby certify that the forego Signed Class C for Signed C	from 3450-3250' (in Class C cement fro NOTE: Notified A s. ed down BOP. Pulle nd cut 4-1/2" casin H with 4-1/2" casin ith tubing to 1163 OH with tubing. WC 60 bbls plug mud fro ng guns and perfora loss in 10 minutes rom 90' to surface oing is rue and correct marker. to office use)	n 4-1/2" casing). om 2460-2260' (in Andy Cortez w/BLM- ed up on 4-1/2" ca ng at 1113'. Rigg ng. Rigged down c '. Mixed and pump DC 4 hours. TIH w rom 990' to surfac ated 4 holes at 60 s. TIH with 2-3/8 <u>Cleaned locatio</u> <u>PLUGGED &amp; ABAND</u> <u>Title</u> <u>PLTROLEUM E</u>	POOH with tub 4-1/2" casing) Hobbs of comme sing. Rigged ed down wireli asing equipmen ed 50 sacks C1 ith tubing and e. POOH w/tub '. Attempt to " tubing to 90 n. Installed ONED - FINAL R Clerk	Mixed and pumped 15 sacks ing to 2460'. Mixed and . POOH with tubing. Shut noing plugging operations up wireline. TIH with ne. Rigged up casing t. Nippled up BOP. SIFN. ass C 2% CaCl2 from tagged top of cement at ing. Rigged up wireline. pump into perfs. Pressured '. Mixed and pumped 30 regulation abandonment EPORT. P & A complete 9-12-
Class C cement : pumped 15 sacks down for night. and cement plugs 9-12-95 - Nipple 3-5/8" cutter an equipment. POOI 9-13-95 - TIH w: 1163-1063'. POO 990'. Spotted & TIH w/perforatin up to 850#) - no sacks Class C fi 14. I hereby certify that the forego Signed	from 3450-3250' (in Class C cement fro NOTE: Notified A s. ed down BOP. Pulle nd cut 4-1/2" casin H with 4-1/2" casin ith tubing to 1163 OH with tubing. WC 60 bbls plug mud fr ng guns and perfora loss in 10 minutes rom 90' to surface oing is rue for correct marker.	n 4-1/2" casing). om 2460-2260' (in Andy Cortez w/BLM- ed up on 4-1/2" ca ng at 1113'. Rigg ng. Rigged down c '. Mixed and pump DC 4 hours. TIH w rom 990' to surfac ated 4 holes at 60 s. TIH with 2-3/8 <u>Cleaned Locatio</u> <u>PLUGGED &amp; ABAND</u> <u>Tide</u> <u>Production</u> Tide <u>PLTROLEUM E</u> the well bore	POOH with tub 4-1/2" casing) Hobbs of comme sing. Rigged ed down wireli asing equipmen ed 50 sacks C1 ith tubing and e. POOH w/tub '. Attempt to " tubing to 90 n. Installed ONED - FINAL R Clerk	Mixed and pumped 15 sacks ing to 2460'. Mixed and . POOH with tubing. Shut ncing plugging operations up wireline. TIH with ne. Rigged up casing t. Nippled up BOP. SIFN. ass C 2% CaCl2 from tagged top of cement at ing. Rigged up wireline. pump into perfs. Pressured '. Mixed and pumped 30 regulation abandonment EPORT. P & A complete 9-12-
Class C cement : pumped 15 sacks down for night. and cement plugs 9-12-95 - Nipple 3-5/8" cutter an equipment. POOI 9-13-95 - TIH w: 1163-1063'. POO 990'. Spotted & TIH w/perforatin up to 850#) - no sacks Class C fi 14. I hereby certify that the forego Signed	from 3450-3250' (in Class C cement fro NOTE: Notified A s. ed down BOP. Pulle nd cut 4-1/2" casin H with 4-1/2" casin ith tubing to 1163 OH with tubing. WC 60 bbls plug mud fro ng guns and perfora loss in 10 minutes rom 90' to surface oing is rue and correct marker. to office use)	n 4-1/2" casing). om 2460-2260' (in Andy Cortez w/BLM- ed up on 4-1/2" ca ng at 1113'. Rigg ng. Rigged down c '. Mixed and pump DC 4 hours. TIH w rom 990' to surfac ated 4 holes at 60 s. TIH with 2-3/8 <u>Cleaned locatio</u> <u>PLUGGED &amp; ABAND</u> <u>Title</u> <u>Production</u> Title <u>PLUGED &amp; ABAND</u> Title <u>PLUGED &amp; ABAND</u> Title <u>PLUGED &amp; ABAND</u> Title <u>PLUGED &amp; ABAND</u>	POOH with tub 4-1/2" casing) Hobbs of comme sing. Rigged ed down wireli asing equipmen ed 50 sacks C1 ith tubing and e. POOH w/tub '. Attempt to " tubing to 90 n. Installed ONED - FINAL R Clerk	Mixed and pumped 15 sacks ing to 2460'. Mixed and . POOH with tubing. Shut ncing plugging operations up wireline. TIH with ne. Rigged up casing t. Nippled up BOP. SIFN. ass C 2% CaCl2 from tagged top of cement at ing. Rigged up wireline. pump into perfs. Pressured '. Mixed and pumped 30 regulation abandonment EPORT. P & A complete 9-12-

Vi do