

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-20274
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. B-155-1
7. Lease Name or Unit Agreement Name NEW MEXICO "O" STATE
8. Well No. 18
9. Pool name or Wildcat VACUUM DRINKARD
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4005' DF

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:  
OIL WELL ☒ GAS WELL ☐ OTHER

2. Name of Operator  
Texaco Exploration and Production Inc.

3. Address of Operator  
P. O. Box 730 Hobbs, NM 88240

4. Well Location  
Unit Letter H : 1880 Feet From The NORTH Line and 560 Feet From The EAST Line  
Section 36 Township 17-S Range 34-E NMPM LEA County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)  
4005' DF

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐  
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER: RECOMPLETED TO VACUUM DRINKARD ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

ABANDONED THE VACUUM UPPPER PENN; RECOMPLETED THE WOLFCAMP TO THE VACUUM DRINKARD

5/4/93 - 7/25/93

1. MIRU, IN WOLFCAMP C/O TO 9460', SET CIBP @ 9460' (RECEIVED NMOCD PERMISSION) & CAPPED W/ 35' CMT, NEW PBTD @ 9425'.
2. IN PENN, C/O TO 9606', SET CIBP @ 9460' & CAP W/ 35' CMT, NEW PBTD @ 9465'.
3. IN ABO, TAGGED CMT @ 265', D/O CMT TO 2588' & TOH.
4. IN WOLFCAMP, SET CIBP @ 7700'. PERFD DRINKARD W/ 2 JSPF FR 7492'-7606' (29 FT - 58 HOLES)
5. SPTD ACID ACROSS PERFS. SET PKR @ 7370', ACIDIZED PERFS W/ 10,000 GALS 20% NEFE. MAX P = 4500#, AIR = 3.4 BPM. SWAB BACK LOAD.
6. TESTED & EVALUATED PRODUCTION. LEFT WELL SI DUE TO UNECONOMICAL PRODUCTION.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Monte C. Duncan TITLE ENGINEER'S ASSISTANT DATE 9-14-93

TYPE OR PRINT NAME MONTE C. DUNCAN TELEPHONE NO. 393-7191

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON  
DISTRICT I SUPERVISOR

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE SEP 15 1993

CONDITIONS OF APPROVAL, IF ANY:

**RECEIVED**

SEP 14 1993

COB ROBERT  
OFFICE