

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form O-103
Revised 12-1-75

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.O.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State ☒ Fee ☐
5. State Oil & Gas Lease No.
B-155-1

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PRODUCTION REPORTS OR FOR OTHER PURPOSES. IT IS A DIFFERENT REPORT. USE OTHER FORMS FOR PRODUCTION REPORTS OR OTHER PURPOSES.)

1. ☒ OIL WELL ☐ GAS WELL ☐ OTHER	7. Unit Agreement Name -
2. Name of Operator TEXACO Inc.	8. Form or Lease Name N.M. 'O' St. NCT-1
3. Address of Operator P. O. Box 728, Hobbs, New Mexico 88240	9. Well No. 18
4. Location of Well UNIT LETTER H 1880 FEET FROM THE North LINE AND 560 FEET FROM THE East LINE, SECTION 36 TOWNSHIP 17-S RANGE 34-E RANGE	10. Field and Pool, or Whichever Vacuum Penn Vacuum Wolfcamp
11. Elevation (Show whether DF, RT, GR, etc.) 4005' (DF)	12. County Lea


16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPER. ☐	PLUG AND ABANDON LNT ☐
FULL OR ALTER CASING ☐	OTHER ☒ Repair Waterflow	CASING TEST AND CEMENT JOB ☐	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1109.

1. Rig up. Install BOP.
2. Set RBP in Wolfcamp above perms. @ approx. 5000'. Repeat procedure in Penn Zone.
3. Log Well. Squeeze csg annulus w/850 sx Class 'C' cement. Test.
4. Pull RBP's & return to production.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED 	TITLE Asst. Dist. Supt.	DATE 8-7-80
ORIG. SIGNED BY Jerry Sexton		
APPROVED BY Dist. 1, Supt.	TITLE	DATE
CONDITIONS OF APPROVAL, IF ANY:		